### Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

**Completion Report** 

API No.: 35133253710000

OTC Prod. Unit No.: 133-227477-0-0000

#### Amended

Amend Reason:

#### Drill Type: STRAIGHT HOLE

Well Name: SANDY 1-31

Location: SEMINOLE 31 8N 6E N2 SE SE NE 2160 FNL 330 FEL of 1/4 SEC Latitude: 35.12433279 Longitude: -96.70617494 Derrick Elevation: 0 Ground Elevation: 900

Operator: REACH OIL AND GAS COMPANY INC 24558

6301 WATERFORD BLVD STE 120 OKLAHOMA CITY, OK 73118-1100 Spud Date: October 29, 2021

Drilling Finished Date: November 04, 2021 1st Prod Date: November 29, 2021

Completion Date: November 29, 2021

Purchaser/Measurer: ENERFIN

First Sales Date:

	Completion Type	Location Exception	1 [	Increased Density
Х	Single Zone	Order No	1	Order No
	Multiple Zone	There are no Location Exception records to display.	1	There are no Increased Density records to display.
	Commingled			

				Casing	and Cem	nent				
	Гуре	Siz	ze Wei	ght	Grade	Fe	et	PSI	SAX	Top of CMT
SURFACE		9 5	5/8 3	6	8RD	794			340	SURFACE
PRODUCTION		5 1	/2 1	7	8RD	4525			110	3730
					Liner					
Туре	Size	Weight	Grade	Le	ength	PSI	SAX	Тор	Depth	Bottom Dept
	1	1	There	are no Li	ner record	ls to displ	ay.			1

## Total Depth: 4574

Pac	ker	Plug			
Depth Brand & Type		Depth	Plug Type		
There are no Packe	r records to display.	There are no Plug records to display.			

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Nov 29, 2021	HUNTON	23	40	200	8695	2	PUMPING	505		

Formation	Name: HUNTON		Code: 269HNTN Class: OIL					
Spacir		Perforated Intervals						
Order No	Unit Size		F	rom	То	1		
718199	80		4351		4375			
Acid	/olumes			Fracture Trea	tments	]		
2500 GAL 28% HCL			There are no Fracture Treatments records to display.			-		
						]		
Formation		Тор		Were open hole lo	gs run? Yes			
HUNTON			4351		November 04, 2021			
SENORA			3037 Were unusual drilling circumstances encour			tered? No		
EARLSBORO			3264	Explanation:				
BARTLESVILLE			3479					
CROMWELL			3642					
WOODFORD			4200					
WOODFORD			4447					
VIOLA								

There are no Other Remarks.

# FOR COMMISSION USE ONLY

Status: Accepted

1147204