1 of 2

Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

Completion Report

API No.: 35019204940000

OTC Prod. Unit No.:

Amended

Amend Reason: REPAIR CASING LEAK. PUT BACK ON INJECTION

Drill Type: SERVICE WELL

SERVICE WELL

Well Name: DHSU C-1

Location: CARTER 4 4S 3W NW NW NW SW 2620 FSL 115 FWL of 1/4 SEC Latitude: 34.238078 Longitude: -97.52656 Derrick Elevation: 970 Ground Elevation: 960

Operator: CITATION OIL & GAS CORPORATION 14156

14077 CUTTEN RD HOUSTON, TX 77069-2212

	Completion Type	Location Exception] [Increased Density
Х	Single Zone	Order No	11	Order No
	Multiple Zone	There are no Location Exception records to display.	1 [There are no Increased Density records to display.
	Commingled			

Casing and Cement										
Туре		Size	Weight	Grade	Fe	et	PSI	SAX	Top of CMT	
PRODUCTION		7	17	J-55	10	25		300	SURFACE	
Liner										
Type Size Weight		Grade Length		PSI	SAX	Top Depth		Bottom Depth		

Total Depth: 1025

Pac	ker	Plug				
Depth	Depth Brand & Type		Plug Type			
650	AD-1	There are no Plug	records to display.			

Initial Test Data

Drilling Finished Date: March 20, 1969

1st Prod Date:

Completion Date: May 29, 1969

Recomplete Date: January 25, 2022

Purchaser/Measurer:

First Sales Date:

Test Date	Formation	Oil BBL/Day	Oil-Gr (AF		Gas CF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
			There	are no Ini	itial Data	a records to disp	olay.				
		Cor	npletio	n and Tes	t Data b	by Producing F	ormation				
Formation Name: HEALDTON					Code: 405HLDN Class: INJ						
	Spacing Orders					Perforated I					
Orde	Order No Unit Size There are no Spacing Order records to display.				From	n 🛛	Т	ō			
There a					700		7	38			
					772		7	77			
					787			03			
					812		8	30			
					927		9	40			
			Fracture Tre	7							
1	NO ADDITIONAL TREATMENT					ADDITIONAL					
Formation		 т	ор								
HEALDTON				6		Were open hole logs run? No Date last log run:					
			/ere unusual dri xplanation:	lling circums	untered? No						

Other Remarks

UIC ORDER #51090

OPERATOR - REPAIR CASING LEAK , TOP OF CASING PATCH @ 6' BOTTOM OF CASING PATCH @ 177' , BAD CASING AT 10' TO 128' ANCHORED PACKER @ 638 TESTED CASING FOR 30 MINUTES 300 PSI . GOOD TEST . APPROVED KELLY COUCH , RETURN TO INJECTION

FOR COMMISSION USE ONLY

Status: Accepted

1147529