## Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35049251970001 **Completion Report** Spud Date: June 01, 2018

OTC Prod. Unit No.: 049-225543-0-0000 Drilling Finished Date: July 12, 2018

1st Prod Date: July 25, 2019

Completion Date: May 09, 2019

First Sales Date: 07/29/2019

**Drill Type: HORIZONTAL HOLE** 

Well Name: BUD 1-12-1WXH Purchaser/Measurer: SOUTHWEST

GARVIN 13 3N 4W Location: NW NW NW NW

170 FNL 270 FWL of 1/4 SEC

Latitude: 34.738707 Longitude: -97.579332 Derrick Elevation: 1182 Ground Elevation: 1162

CASILLAS OPERATING LLC 23838 Operator:

> 401 S BOSTON AVE STE 2400 TULSA, OK 74103-4060

	Completion Type
Χ	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
703862

Increased Density
Order No
688079

		Cas	sing and Ceme	nt			
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40.00	J-55	1512		443	SURFACE
PRODUCTION	5.5	20.00	P-110EC	23012		2115	6456

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
			There are	no Liner record	ds to displa	ay.		

Total Depth: 23012

Pac	ker
Depth	Brand & Type
There are no Packe	r records to display.

Ple	ug			
Depth Plug Type				
There are no Plug	records to display.			

				Initial Tes	t Data					
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Oct 03, 2019	WOODFORD	391	46	1682	4302	851	FLOWING	1747	64/64	1878

February 19, 2020 1 of 2

### **Completion and Test Data by Producing Formation**

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders					
Order No	Unit Size				
677714	640				
703861	MULTIUNIT				

Perforated Intervals					
From	То				
12598	22867				

Acid Volumes
810 BBLS HCL ACID

Fracture Treatments
588,042 BBLS FLUID 18,932,085 LBS PROPPANT

Formation	Тор
WOODFORD	12340

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? Yes Explanation: TWO SIDETRACKS DUE TO GEOLOGIC INTEGRITY ISSUES. NO TOOLS LEFT DOWNHOLE.

## Other Remarks

There are no Other Remarks.

#### Lateral Holes

Sec: 1 TWP: 3N RGE: 4W County: GARVIN

NE NW NW NW

21 FNL 479 FWL of 1/4 SEC

Depth of Deviation: 12134 Radius of Turn: 330 Direction: 1 Total Length: 10269

Measured Total Depth: 23012 True Vertical Depth: 11692 End Pt. Location From Release, Unit or Property Line: 50

# FOR COMMISSION USE ONLY

1143718

Status: Accepted

February 19, 2020 2 of 2