Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

OTC Prod. Unit No.: 141-230270 Drilling Finished Date: August 08, 2022

1st Prod Date: October 03, 2022

Completion Date: October 03, 2022

Drill Type: STRAIGHT HOLE

Well Name: GRIFFIN 1 Purchaser/Measurer:

Location: TILLMAN 7 3S 18W SW NE NW SE

400 FNL 965 FWL of 1/4 SEC

Latitude: 34.31143 Longitude: -99.120478

Derrick Elevation: 1269 Ground Elevation: 1263

Operator: AC OPERATING COMPANY LLC 23061

952 ECHO LN STE 390 HOUSTON, TX 77024-2851

Completion Type					
Х	Single Zone				
	Multiple Zone				
	Commingled				

Location Exception					
Order No					
There are no Location Exception records to display.					

Increased Density						
Order No						
There are no Increased Density records to display.						

First Sales Date:

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	8 5/8	24	J-55	204		150	SURFACE	
PRODUCTION	5 1/2	15.5	J-55	5386		275	3590	

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 5457

Packer					
Depth Brand & Type					
There are no Packer records to display.					

Plug					
Depth Plug Type					
There are no Plug records to display.					

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Nov 04, 2022	STRAWN	100	41			20	PUMPING		OPEN	

December 09, 2022 1 of 2

Completion and Test Data by Producing Formation Formation Name: STRAWN Code: 404STRN Class: OIL **Spacing Orders Perforated Intervals** Order No **Unit Size** То From NONE 5218 5232 **Acid Volumes Fracture Treatments** 1,500 GALLONS 15% There are no Fracture Treatments records to display.

Formation	Тор
HENDERSON	3292
CANYON	3410
STRAWN	4268
MISSISSIPPIAN	5353

Were open hole logs run? No Date last log run: August 24, 2022

Were unusual drilling circumstances encountered? No

Explanation:

Other	Rem	arks
-------	-----	------

There are no Other Remarks.

FOR COMMISSION USE ONLY

1149278

Status: Accepted

December 09, 2022 2 of 2