Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35059215440002 **Completion Report** Spud Date: April 27, 1988

OTC Prod. Unit No.: Drilling Finished Date: May 17, 1988

1st Prod Date: August 11, 1988

Amend Reason: ATTEMPTED RECOMPLETION NOT DONE (SEE REMARKS)

Completion Date: August 03, 1988

Recomplete Date: August 14, 2021

Drill Type: STRAIGHT HOLE

Amended

Well Name: TIPPING 15-3 Purchaser/Measurer:

Location: HARPER 15 27N 21W

C NE NW

1980 FSL 1980 FWL of 1/4 SEC

Derrick Elevation: 0 Ground Elevation: 1736

MARJO OPERATING MID-CONTINENT LLC 23610 Operator:

PO BOX 729

427 S BOSTON AVE STE 240 TULSA, OK 74101-0729

Completion Type
Single Zone
Multiple Zone
Commingled

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

First Sales Date:

Casing and Cement									
Type Size Weight Grade Feet PSI SAX Top of Cl									
CONDUCTOR	20	67	X-42	100					
SURFACE	8 5/8	24	J-55	850		400	SURFACE		
PRODUCTION	4 1/2	10.5 & 11.6	J-55 & N-80	7706		660	4140		

				Liner							
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth			
	There are no Liner records to display.										

Total Depth: 7700

Packer								
Depth Brand & Type								
There are no Packe	er records to display.							

PI	ug
Depth	Plug Type
3360	CIBP
5750	CIBP

Initial Test Data

September 03, 2021 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
	There are no Initial Data records to display.									
	Completion and Test Data by Producing Formation									
Formation Name: NONE Code						С	lass: DRY			
Formation		T	ор	v	/ere open hole l	ogs run? No				
SEE ORIGINA	L 1002A'S			0 D	0 Date last log run:					

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

THIS WAS AN EXISTING WELL THAT WAS PRODUCING FROM THE KANSAS CITY LIME AND HAD BEEN TEMPORARILY ABANDONED. MARJO RE-ENTERED THIS WELL TO TEST ANOTHER KANSAS CITY ZONE. WE RAN IN WITH TUBING AND A CASING SCRAPER. WE GOT TO 3,400' AND ENCOUNTERED MUD AND SHALE. WE DECIDED THAT POTENTIAL WELL PROBLEMS WERE TOO GREAT AND DECIDED TO PLUG THE WELL. WE NEVER TESTED THE KANSAS CITY ZONE. SEE FORM 1003 FOR PLUGGING DETAILS. OCC - SET CIBP AT 3,360'.

FOR COMMISSION USE ONLY 1146853 Status: Accepted

September 03, 2021 2 of 2

.02

NO. 059-21544 OTC PROD. NA UNIT NO. NA Oil and Gas Conservation Division
P.O. Box 52000
Oklahoma City, OK 73152-2000
405-521-2331
OCCCentralProcessing@OCC.OK.GOV



Form 1002A Rev. 2020

ORIGINAL AMENDED (Resson)	Attempl	ed Re	comple	etion No	er De	one comp	LETION REPO	RT			
YPE OF DRILLING OPERATIO	ON DIRECTIONAL HO		KENTON THORIZON	TAL HOLE	SPUC	DATE 4	-27-1988	7 -		640 Acres	
SERVICE WELL			HURIZUN	TAL HOLE	DRLG	EINISHED	-17-198			1	
directional or horizontal, see re-			VP 27N RG	E 2414/	DATE	OF WELL	8/19/21		/		
EASE Harper		15 11		***	-	PLETION					
AME	Tipping	1	NC	15-3	_	ROD DATE	8-11-19	1 \\\			
	1/4 N 1/4	FSL 19	80 F	WL1980	RECO	OMP DATE	8/14/2021	∟ "Ի		*	
LEVATION Groun	¹⁷³⁶	Latitude			Longi						
PERATOR Marjo C	Operating M	Ild-Cont	inent LL		C/OCC		23610		-		
DDRESS	1		O. Box	10.	LIVITO					\vdash	
тү	Tulsa				OK	ZIP	74101				
COMPLETION TYPE	Tuisa			& CEMENT (17101			OCATE WE	L
SINGLE ZONE				PE	SIZE	WEIGHT	GRADE	FEET	PSI	SAX	TOP OF CMT
MULTIPLE ZONE			CONDUC	TOR	20	67	×42	100			
Application Date COMMINGLED			SURFACI		8 5/8	24#	J55	850		400	Surface
LOCATION EXCEPTION			INTERME								
ORDER NO. MULTIUNIT ORDER NO.			PRODUC	TION A	4 1/2	10.5#	J56	7706		660	4140
NCREASED DENSITY			LINER			(11,6)	NED				
ORDER NO	ID 4 7/05		F1.150.0	3360	TYPE			TYPE		TOTAL	
	ID & TYPE		PLUG @	5780	TYPE		PLUG @	TYPE		DEPTH	7700'
COMPLETION & TEST DATA		FORMATI	_								
FORMATION	N/	4			1						
SPACING & SPACING					+						
ORDER NUMBER											
CLASS: Oll, Gas, Dry, Inj,	Dry		7								
Disp, Comm Disp, Svc											
PERFORATED											
NTERVALS			+						11 11 15		1 A F
									<u> </u>	EP 01	2021
ACIDIVOLUME									J	- 0 -	LULI
									OKIVA	OMA CO	RPORATIO
										COMMIS	
FRACTURE TREATMENT (Fluids/Prop Amounts)											01011
a second a tab t discourse.											
		Min Gas A		165:10-17-7)				urchaser/Measure rst Seles Date	er		
NITIAL TEST DATA	<u> </u>	Oll Alto		166:10-13-3)				ist Sales Date			
NITIAL TEST DATE	N/	4									
OIL-BBL/DAY											
DIL-GRAVITY (API)											
GAS-MCF/DAY											
					-					_	
GAS-OIL RATIO CU FT/8BL			-			,				+	
WATER-BBL/DAY			-		-						
PUMPING OR FLOWING					-					-+	
NITIAL SHUT-IN PRESSURE											
CHOKE SIZE											
FLOW TUBING PRESSURE			-								
A record of the formations dril to make this report, which was	led through, and pe	rtinent remar	ks are preser	ited on the reve	the date	eclare that I he	ave knowledge of	the contents of th	is report and am	authorized b	y my organizatio
o make his rability miles was	, propertod by Ille O	and my su	Port amount of the	avenous, mail		Keefer	LE TROUBLE DE L		8/27/202		18583024
SIGNA			-	NA		INT OR TYP	E)		DATE	Pl	HONE NUMBER
P.O. Bo			Tuls		OK	7410	<u> </u>	bri	ian@marj		n
ADDR	ESS		CIT	Υ	STATE	ZIP			EMAIL ADD	RESS	

PLEASE TYPE OR USE BLACK INK ONLY FORMATION RECORD Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested. Tipping 15-3 LEASE NAME WELL NO. NAMES OF FORMATIONS FOR COMMISSION USE ONLY see original 100ZA's ITD on file APPROVED DISAPPROVED 2) Reject Codes O ves O no Were open hole logs run? None Run Date Last log was run Was CO₂ encountered? at what depths? Was H₂S ancountered? Were unusual drilling circumstances encountered? f yes, briefly explain below This was an existing well that was producing from the Kansas City Lime and had been TA'd. Marjo re-entered this well to test another Kansas City zone. We ran in with tbg and a casing scraper. We got to 3400' and encountered mud and shale. We decided that potential well problems were too great and decided to plug the well. We never tested the Kansas City zone. See form 1003 for plugging details. CIBP at 3360 BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE SEC RGE COUNTY TWP Feet From 1/4 Sec Lines SHL From Lease, Unit, or Property Line: **BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)** RGE COUNTY TWF Feet From 1/4 Sec Lines Radius of Turn separate sheet indicating the necessary information. True Vertical Depth BHL From Lease, Unit, or Prope Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the RGE lease or specing unit. Directional surveys are required for all drainholes 1/4 Feet From 1/4 Sec Lines and directional wells Depth of Radius of Turn Total Deviation Measured Total Depth Length BHL From Lease, Unit, or Property Line: True Vertical Depth LATERAL # Feet From 1/4 Sec Lines Radius of Turn Depth of Total Deviation Measured Total Depth Length BHL From Lease, Unit, or Property Line: True Vertical Depth