Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35049236110001 **Completion Report** Spud Date: July 04, 1991

OTC Prod. Unit No.: 049-0261711-1-0000 Drilling Finished Date: August 13, 1991

1st Prod Date: September 06, 1991

Amended Completion Date: September 06, 1991

Recomplete Date: September 18, 2019

Amend Reason: RECOMPLETION

Drill Type: STRAIGHT HOLE

Well Name: JOHNSON 1-34 Purchaser/Measurer: DCP

Location: GARVIN 34 1N 3W

C NE NE NE 330 FNL 330 FEL of 1/4 SEC

Derrick Elevation: 955 Ground Elevation: 943

ARDMORE PRODUCTION & EXPLORATION CO 16133 Operator:

PO BOX 1988

301 W MAIN ST STE 415 ARDMORE, OK 73402-1988

	Completion Type
Х	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
701988

First Sales Date:

Casing and Cement							
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	16			43			
SURFACE	9 5/8	36	J-55	827		850	SURFACE
PRODUCTION	5 1/2	17/15.5	K-55/J-55	4223		850	1670

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
	There are no Liner records to display.							

Total Depth: 6686

Packer				
Depth Brand & Type				
There are no Packer records to display.				

Plug			
Depth	Plug Type		
5010	CIBP		
6072	CIBP		

Initial Test Data

November 21, 2019 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Sep 19, 2019	GOODWIN MID	15	28	5	300		PUMPING			

Completion and Test Data by Producing Formation

Formation Name: GOODWIN MID

Code: 401GDWNM

Class: OIL

Spacing Orders				
Order No	Unit Size			
65411	40			

Perforated Intervals				
From	То			
4860	4930			

Acid Volumes
1,500 GALLONS 7.5% HCL

Fracture Treatments	
1,050 BARRELS OIL, 45,000 POUNDS 20/40	

Formation	Тор
MARKHAM	2060
HUMPHREYS	3210
SIMS	3492
UPPER GOODWIN	3981
MIDDLE GOODWIN	4900
SYCAMORE	6122
WOODFORD	6502

Were open hole logs run? Yes Date last log run: August 09, 1991

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

CIBP SET AT 6,072' WITH + 10' (2 SACKS) OF CEMENT DUMPED WITH BAILER BY ARBUCKLE WIRELINE ON FEBRUARY 4, 2019. SHOT FOUR SQUEEZE HOLES AT 4,860' TO 4,861' AND COULD NOT PUMP INTO THE BACKSIDE. DRILLED CEMENT TO 5,024' AND STOPPED, DID NOT DRILL OUT OF CEMENT. SET CIBP AT 5,010' TO ISOLATE BELOW. CEMENT BOND LOG RUNS INDICATED THAT TOP OF GOOD CEMENT IS 1,760' AND SPOTTY CEMENT TO 350' FROM SURFACE.

FOR COMMISSION USE ONLY

1143820

Status: Accepted

November 21, 2019 2 of 2


PLEASE TYPE OR USE BLACK INK ONLY FORMATION RECORD

Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested.

NAMES OF FORMATIONS	ТОР
	(MD)
Markham	2,060
Humphreys	3,210
Sims	3,492
Upper Goodwin	3,981
Middle Goodwin	4,900
Sycamore	6,122
Woodford	6,502

	FOR	COMMISSION USE ONLY
	ES NO	?) Reject Codes
	- - - -	
Were open hole logs run' Date Last log was run		no 8/9/1991
Was CO ₂ encountered? Was H ₂ S encountered?	yes	X no at what depths?
Were unusual drilling circ If yes, briefly explain belo	cumstances encountered	

Other remarks: CIBP set at 6072' with +10 feet (2 sks) of cement dumped with bailer by Arbuckle Wireline on 2/4/19. Shot four sqz holes at 4860' to 4861' and could not pump into the backside. Drilled cement to 5024 and stopped, did not drill out of cement. Set CIBP at 5010' to isolate below. CBL runs indicated that top of good cement is 1760' and spotty cement to 350' from surface.




If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth.

Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.



BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC TWP	RGE		COUNTY			
Spot Location 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Measured Total Depth		True Vertical De		BHL From Lease, Unit, or Pr	operty Line:	B1101 2 222

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

SEC	TWP	RGE		COUNTY			
Spot Loc	cation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation	n		Radius of Turn		Direction	Total Length	in it is
Measure	ed Total Depth		True Vertical De	pth	BHL From Lease, Unit, or Pr		Frank Art 1889

SEC TWP RGE COUNTY Spot Location Feet From 1/4 Sec Lines FSL FWL 1/4 1/4 1/4 Depth of Radius of Turn Total Deviation Measured Total Depth Length True Vertical Depth BHL From Lease, Unit, or Property Line:

SEC	TWP	RGE		COUNTY		1.17	, Kara Tabura
Spot Loc	ation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation			Radius of Turn		Direction	Total Length	Beere
Measured Total Depth True Vertical Dep		pth	BHL From Lease, Unit, or Property Line:				