

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35017224730000

Completion Report

Spud Date: December 15, 1982

OTC Prod. Unit No.:

Drilling Finished Date: January 05, 1983

Amended

1st Prod Date: January 26, 1983

Amend Reason: PERFORMED ACID JOB; UPDATED TEST INFORMATION

Completion Date: January 28, 1983

Recomplete Date: September 06, 2018

Drill Type: STRAIGHT HOLE

Well Name: O U 2

Purchaser/Measurer:

Location: CANADIAN 31 14N 8W
C SE NW SW
1650 FSL 990 FWL of 1/4 SEC
Latitude: 35.642846636 Longitude: -98.097201626
Derrick Elevation: 1420 Ground Elevation: 1402

First Sales Date:

Operator: URBAN OIL & GAS GROUP LLC 22756

1000 E 14TH ST STE 300
PLANO, TX 75074-6220

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	230316		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8 5/8	24	K-55	1006		550	SURFACE
PRODUCTION	4 1/2	10.4 / 11.6	K-55	8112		400	7020

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 8120

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
7986	AS1-X	There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Feb 05, 2019	COTTAGE GROVE	6	39			156	PUMPING		64/64	

Completion and Test Data by Producing Formation

Formation Name: COTTAGE GROVE

Code: 405CGGV

Class: OIL

Spacing Orders

Order No	Unit Size
206554	640

Perforated Intervals

From	To
8024	8036

Acid Volumes

2,500 GALS 15% HCL ACID
45 BBLS 2% KCL ACID FLUSH

Fracture Treatments

NO ADDITIONAL FRAC TREATMENT

Formation	Top
TONKAWA	7350
COTTAGE GROVE	8020

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

OPERATOR - CLEANED OUT WELLBORE, ACIDIZED

OCC - OPERATOR UPDATED CEMENT TOPS

FOR COMMISSION USE ONLY

1144911

Status: Accepted