

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35123238820002

Completion Report

Spud Date: April 05, 2018

OTC Prod. Unit No.: 123-223424

Drilling Finished Date: April 11, 2018

Amended

1st Prod Date: April 24, 2018

Amend Reason: RECOMPLETION TO SENORA FORMATION

Completion Date: April 23, 2018

Recomplete Date: March 24, 2023

Drill Type: STRAIGHT HOLE

Min Gas Allowable: Yes

Well Name: BRAUM 5-9

Purchaser/Measurer:

Location: PONTOTOC 9 5N 4E
SE SE NW NE
1155 FNL 1485 FEL of 1/4 SEC
Latitude: 35.923833 Longitude: -96.882583
Derrick Elevation: 1003 Ground Elevation: 988

First Sales Date:

Operator: GULF EXPLORATION LLC 20983

9701 N BROADWAY EXT
OKLAHOMA CITY, OK 73114-6316

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	681628		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	16	44	A-242	40	500	6	SURFACE
SURFACE	8 5/8	24	J-55	168	1000	150	SURFACE
PRODUCTION	5 1/2	17	N-80	3370	200	280	1870

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 3400

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		2820	CIBP

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Apr 03, 2023	SENORA	9.6	34			1	PUMPING	84		

Completion and Test Data by Producing Formation			
Formation Name: SENORA		Code: 404SNOR	
Class: OIL			
Spacing Orders		Perforated Intervals	
Order No	Unit Size	From	To
671554	40	2592	2606
Acid Volumes		Fracture Treatments	
1,000 GALLONS 7.5%		22,756 GALLONS 30 POUNDS LINEAR GEL, 29,161 POUNDS 16/30	

Formation	Top
SENORA	2562

Were open hole logs run? Yes
 Date last log run: April 10, 2018

Were unusual drilling circumstances encountered? No
 Explanation:

Other Remarks
BY OPERATOR- YES, THE OPEN HOLE LOGS WERE SENT AT THE TIME THE WELL WAS DRILLED.

FOR COMMISSION USE ONLY	
Status: Accepted	1149900