

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35123235030003

Completion Report

Spud Date: March 10, 2004

OTC Prod. Unit No.:

Drilling Finished Date: April 08, 2004

Amended

1st Prod Date:

Amend Reason: TEMPORARILY ABANDONED

Completion Date: April 08, 2004

Drill Type: STRAIGHT HOLE

Well Name: NE FITTS UNIT 10-6

Purchaser/Measurer:

Location: PONTOTOC 23 2N 7E
C SE NW NW
1650 FSL 990 FWL of 1/4 SEC
Derrick Elevation: 727 Ground Elevation: 719

First Sales Date:

Operator: ENERGYQUEST II LLC 22708

4526 RESEARCH FOREST DR STE 200
THE WOODLANDS, TX 77381-4079

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	There are no Location Exception records to display.		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8 5/8	23	K-55	524	350	400	SURFACE
PRODUCTION	5 1/2	14	K-55	4142	350	719	SURFACE

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 4150

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
There are no Initial Data records to display.										

Completion and Test Data by Producing Formation			
Formation Name: HUNTON		Code: 269HNTN	Class: TA
Spacing Orders		Perforated Intervals	
Order No	Unit Size	From	To
There are no Spacing Order records to display.		3974	4030
Acid Volumes		Fracture Treatments	
There are no Acid Volume records to display.		There are no Fracture Treatments records to display.	

Formation	Top
SEE ORIGINAL 1002A (COMPLETION REPORT)	0

Were open hole logs run? No
Date last log run:

Were unusual drilling circumstances encountered? No
Explanation:

Other Remarks
OCC - RESTORING 1002A AFTER NET WORK GOING DOWN NO CHANGE FROM THE ORIGINAL APPROVAL 10/18/2017.

FOR COMMISSION USE ONLY	
Status: Accepted	1137737