

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35087220700000

Completion Report

Spud Date: March 30, 2017

OTC Prod. Unit No.: 087218831

Drilling Finished Date: April 17, 2017

1st Prod Date: June 10, 2017

Completion Date: May 22, 2017

Drill Type: HORIZONTAL HOLE

Well Name: MAXIMUS 1-19-18 WXH

Purchaser/Measurer: WOODFORD EXPRESS

Location: MCCLAIN 30 5N 4W
NE NE NE NW
280 FNL 2325 FWL of 1/4 SEC
Latitude: 34.88343 Longitude: -97.66253
Derrick Elevation: 1035 Ground Elevation: 1012

First Sales Date: 6/10/17

Operator: CASILLAS OPERATING LLC 23838

401 S BOSTON AVE STE 2400
TULSA, OK 74103-4060

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	676782		There are no Increased Density records to display.	
	Commingle				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40.0	J55	1507		395	SURFACE
PRODUCTION	5.50	20.0	P110	17530		1625	5727

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 17560

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jun 17, 2017	WOODFORD	134	48	6726	50194	453	FLOWING		64/128	980

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders

Order No	Unit Size
636308	640
636309	640
638755	MULTIUNIT

Perforated Intervals

From	To
10342	17423

Acid Volumes

405 BBLS HCL ACID

Fracture Treatments

512,985 BBLS FLUID 18,291,140 LBS PROPPANT

Formation	Top
WOODFORD	9919

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

OCC - THIS DOCUMENT IS ACCEPTED BASED ON DATA SUBMITTED, THE FINAL MULTIUNIT HAS NOT BEEN ISSUED. MULTIUNIT ORDER 662986 MODIFIES ORDER 638755 TO CHANGE OPERATOR TO CASILLAS OPERATING, LLC. EXCEPTION TO RULE - 676782 165:10-3-28(C)(2)(B). LOCATION EXCEPTION 676782 PARAGRAPH 7, STATES THE WELL NAME AS THE CUADRILLA 1-3-10XH, WHICH SHOULD BE THE MAXIMUS 1-19-18 WXH, WILL BE CORRECTED BY NUNC PRO TUNC PER ATTORNEY FOR OPERATOR. MULTIUNIT ORDER - 650282 EXTENDS 638755

Lateral Holes

Sec: 18 TWP: 5N RGE: 4W County: MCCLAIN

SW NW NE SW

2132 FSL 1496 FWL of 1/4 SEC

Depth of Deviation: 9575 Radius of Turn: 662 Direction: 358 Total Length: 7323

Measured Total Depth: 17560 True Vertical Depth: 9642 End Pt. Location From Release, Unit or Property Line: 1496

FOR COMMISSION USE ONLY

1136846

Status: Accepted