## Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

API No.: 35053234590000

Well Name: STATE 1-33

Drill Type:

Location:

OTC Prod. Unit No.: 053-222757-0-0000

STRAIGHT HOLE

GRANT 33 25N 3W

NW NW NW NW 165 FNL 165 FWL of 1/4 SEC **Completion Report** 

Spud Date: November 25, 2017

Drilling Finished Date: December 05, 2017

1st Prod Date:

Completion Date: January 05, 2018

Purchaser/Measurer:

First Sales Date:

Operator: TERRITORY RESOURCES LLC 22388

Latitude: 36.60752903 Longitude: -97.533593647 Derrick Elevation: 1062 Ground Elevation: 1049

1511 S SANGRE RD STILLWATER, OK 74074-1869

	Completion Type	Location Exception	Increased Density			
Х	Single Zone	Order No	Order No			
	Multiple Zone	There are no Location Exception records to display.	There are no Increased Density records to display.			
	Commingled					

Casing and Cement											
Туре		Si	ze	Weight	Grade	Fe	et	PSI SAX		Top of CMT	
SURFACE		8 5	6/8"	24	J55	20	08		150	SURFACE	
PRODUCTION		5 1	/2"	15.5	J55	58	36		225	4411	
Liner											
Туре	Size	Weight	G	Grade	Length	PSI	SAX	Тор	Depth	Bottom Depth	
There are no Liner records to display.											

## Total Depth: 5840

Pac	ker	Plug			
Depth	Brand & Type	Depth	Plug Type		
There are no Packe	r records to display.	There are no Plug	records to display.		

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Jan 05, 2018	WILCOX	203				51	FLOWING		2"	46

	Completion and Test Data by Producing Formation								
Formation Na	ame: WILCOX	Code: 202WLCX Class: OIL							
Spacing	Orders	Perforated In	tervals						
Order No	Order No Unit Size		То						
668809	80	5687	5704						
670133	MODIFY	5709	5712						
Acid Vo	olumes	Fracture Treatments							
PUMPED 5,000 GALS 10% KCL, TLTR:		NONE							

Formation	Тор		Were open hole logs run? Yes
TONKAWA		3532	Date last log run: December 04, 2017
LAYTON		4075	Were unusual drilling circumstances encountered? No
OSWEGO		4594	Explanation:
MISSISSIPPIAN		5115	
WOODFORD		5601	
WILCOX		5686	

## Other Remarks

WELL HAS NOT HAD 1ST SALES YET DUE TO PENDING HEARING. INITIAL 24 HOUR PRODUCTION CALCULATED FROM 6 HOUR TEST. OCC -PER OPERATOR WELL STILL NOT PRODUCING AS OF 2/13/2020. OCC - THE LOCATION EXCEPTION CD # 201704990 WAS DISMISSED BY ORDER 687686. OCC- WELL IS OFF PATTERN AND WILL REQUIRE A LOCATION EXCEPTION TO PRODUCE. OCC - OPERATOR SET PORT COLLAR AT 4922' AND USED 100 SACKS OF CEMENT TO LIFT CEMENT TO CALCULATED TOP OF CEMENT AT 4422' SEE 1002C FOR PORT COLLAR.

## FOR COMMISSION USE ONLY

Status: Accepted