## Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35019264200001 **Completion Report** Spud Date: January 14, 2021

OTC Prod. Unit No.: Drilling Finished Date: January 15, 2021

1st Prod Date: May 24, 2021

Amend Reason: SET CIBP PERFORATED SHALLOWER CISCO

Completion Date: February 25, 2021 Recomplete Date: November 15, 2021

**Drill Type:** STRAIGHT HOLE

Amended

Well Name: PWF 3511 8 Purchaser/Measurer:

Location: CARTER 35 3S 2W NE SE NW SE

1815 FSL 1485 FEL of 1/4 SEC

Latitude: 34.250339 Longitude: -97.374255 Derrick Elevation: 976 Ground Elevation: 972

ARDMORE PRODUCTION & EXPLORATION CO 16133 Operator:

PO BOX 1988

ARDMORE, OK 73402-1988

Completion Type					
Χ	Single Zone				
	Multiple Zone				
Commingled					

Location Exception					
Order No					
There are no Location Exception records to display.					

Increased Density					
Order No					
There are no Increased Density records to display.					

First Sales Date:

Casing and Cement							
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
PRODUCTION	5.5	17	K-55	1085		200	SURFACE

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 1105

Packer					
Depth Brand & Type					
There are no Packer records to display.					

Plug					
Depth	Plug Type				
905	COMPOSITE				

	Initial Test Data									
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Nov 16, 2021	CISCO					20	PUMPING			

June 27, 2022 1 of 2

Completion and Test Data by Producing Formation							
Formation N	Name: CISCO	Code: 406CSCO	Class: DRY				
Spacing	g Orders	Perforated In	tervals				
Order No	Unit Size	From	То				
There are no Spacing Order records to display.		800	838				
Acid V	olumes	Fracture Trea	tments				
NONE		NONE					

Formation	Тор
CISCO	560

Were open hole logs run? Yes
Date last log run: January 15, 2021

Were unusual drilling circumstances encountered? No Explanation:

## Other Remarks

COMPOSITE BRIDGE PLUG WAS SET WITH 5' OF CEMENT ON TOP AT 905'. THIS ISOLATES THE CISCO PERFORATIONS 928' - 941' FROM THE CISCO PERFORATIONS 800' - 838'. BREAKDOWN WITH 120 BARRELS OF 2% KCL, SUB AND SURFACTANT. 800' - 838' APPEAR TO PRODUCE FRESH WATER. +4X LOAD PRODUCED BACK. WATER SAMPLE COLLECTED BY OCC FIELD INSPECTOR.

## FOR COMMISSION USE ONLY

1148296

Status: Accepted

June 27, 2022 2 of 2