

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35111275460000

Completion Report

Spud Date: April 06, 2022

OTC Prod. Unit No.:

Drilling Finished Date: April 13, 2022

1st Prod Date: June 09, 2022

Completion Date: June 01, 2022

Drill Type: STRAIGHT HOLE

Well Name: DOUBLE E 1

Purchaser/Measurer:

Location: OKMULGEE 17 15N 11E
NE SW SE SE
520 FSL 840 FEL of 1/4 SEC
Latitude: 35.77133 Longitude: -96.16031
Derrick Elevation: 870 Ground Elevation: 0

First Sales Date:

Operator: ENTERPRISE ENERGY EXPLORATION INC 21418

6528 E 101ST ST STE 392
TULSA, OK 74133-6724

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
There are no Location Exception records to display.	

Increased Density	
Order No	
There are no Increased Density records to display.	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8 5/8	24	L.S.	158	500	100	SURFACE
PRODUCTION	5 1/2	15.50	J-55	3025	800	100	2190

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 3046

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jun 09, 2022	MISENER	10	39			50	PUMPING	80		

Completion and Test Data by Producing Formation			
Formation Name: MISENER		Code: 319MSNR	Class: OIL
Spacing Orders		Perforated Intervals	
Order No	Unit Size	From	To
There are no Spacing Order records to display.		2973	2981
Acid Volumes		Fracture Treatments	
750 GALLONS 7.5%		There are no Fracture Treatments records to display.	

Formation	Top
BARTLESVILLE	2030
BOOTH	2330
DUTCHER	2530
MISENER	2970
WILCOX	3030

Were open hole logs run? Yes
Date last log run: August 14, 2021

Were unusual drilling circumstances encountered? No
Explanation:

Other Remarks
There are no Other Remarks.

FOR COMMISSION USE ONLY	
Status: Accepted	1148357