

Oklahoma Corporation Commission  
Oil & Gas Conservation Division  
Post Office Box 52000  
Oklahoma City, Oklahoma 73152-2000  
Rule 165: 10-3-25

Form 1002A

API No.: 35047251850000

**Completion Report**

Spud Date: February 07, 2019

OTC Prod. Unit No.: 04722544000000

Drilling Finished Date: February 22, 2019

1st Prod Date: May 11, 2019

Completion Date: May 11, 2019

**Drill Type: HORIZONTAL HOLE**

Well Name: BLACKBURN 36-23N-05W 1MH

Purchaser/Measurer: MUSTANG GAS PRODUCTS LLC

First Sales Date: 05/11/2019

Location: GARFIELD 25 23N 5W  
SE SW SE SW  
190 FSL 1670 FWL of 1/4 SEC  
Latitude: 36.434552 Longitude: -97.687315  
Derrick Elevation: 1202 Ground Elevation: 1179

Operator: CONTANGO RESOURCES INC 24432

717 TEXAS AVE STE 2900  
HOUSTON, TX 77002-2836

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	712660		690317	
	Commingled				

Casing and Cement								
Type		Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE		9-5/8	36	J-55	397		200	SURFACE
INTERMEDIATE		7	26	P-110	6165		215	2734

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4-1/2	13.5	P-110	5896	0	0	5072	10968

**Total Depth: 10968**

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
6093	5-1/2" BAKER	There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
May 10, 2019	MISSISSIPPI LIME	623	41	1416	2273	4856	PUMPING		26/64	246

Completion and Test Data by Producing Formation			
Formation Name: MISSISSIPPI LIME		Code: 351MSSLM	Class: OIL
<b>Spacing Orders</b>		<b>Perforated Intervals</b>	
<b>Order No</b>	<b>Unit Size</b>	<b>From</b>	<b>To</b>
77383	640	6363	10944
<b>Acid Volumes</b>		<b>Fracture Treatments</b>	
2673 BLS 10% HCL		120385 BLS H2O 3948680 LBS SAND	

Formation	Top
MISSISSIPPI LIME	5969

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks
LINER NOT CEMENTED, OPEN-HOLE COMPLETION BHL FROM PROPOSED PLAT

Lateral Holes
Sec: 36 TWP: 23N RGE: 5W County: GARFIELD  SW SW SE SW  165 FSL 844 FWL of 1/4 SEC  Depth of Deviation: 5209 Radius of Turn: 877 Direction: 178 Total Length: 4383  Measured Total Depth: 10968 True Vertical Depth: 6094 End Pt. Location From Release, Unit or Property Line: 165

FOR COMMISSION USE ONLY	
Status: Accepted	1144816