

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35073264100000

Completion Report

Spud Date: January 15, 2019

OTC Prod. Unit No.: 07322572400000

Drilling Finished Date: January 31, 2019

1st Prod Date: July 13, 2019

Completion Date: July 13, 2019

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: HAROLD 16_9-15N-9W 2HX

Purchaser/Measurer: ENLINK

Location: KINGFISHER 16 15N 9W
SE SW SW SE
265 FSL 2006 FEL of 1/4 SEC
Latitude: 35.76938762 Longitude: -98.16045544
Derrick Elevation: 1238 Ground Elevation: 1208

First Sales Date: 07/13/2019

Operator: DEVON ENERGY PRODUCTION CO LP 20751

333 W SHERIDAN AVE
OKLAHOMA CITY, OK 73102-5015

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	704647		691713	
	Commingled			691712	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	20	106.5	K-55	70			0
SURFACE	9 5/8	40	J-55	1990		465	SURFACE
PRODUCTION	5 1/2	20	P-110EC	20254		2655	SURFACE

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 20268

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		20046	ALUMINUM

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Aug 15, 2019	MISSISSIPPIAN	413	50.7	1962	4750	437	FLOWING	1651	28	634

Completion and Test Data by Producing Formation

Formation Name: MISSISSIPPIAN

Code: 359MSSP

Class: OIL

Spacing Orders

Order No	Unit Size
660240	640
657991	640
704646	MULTIUNIT

Perforated Intervals

From	To
10219	20031

Acid Volumes

NONE

Fracture Treatments

308448 BBLS OF TOTAL FLUID 27136021 # OF TOTAL PROPPANT
--

Formation	Top
MISSISSIPPIAN	9707

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

IRREGULAR SECTION

Lateral Holes

Sec: 9 TWP: 15N RGE: 9W County: KINGFISHER

NW NW NE NW

50 FNL 1430 FWL of 1/4 SEC

Depth of Deviation: 9492 Radius of Turn: 607 Direction: 360 Total Length: 9821

Measured Total Depth: 20268 True Vertical Depth: 9645 End Pt. Location From Release, Unit or Property Line: 50

FOR COMMISSION USE ONLY

1143005

Status: Accepted