Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35107230170001 **Completion Report** Spud Date: July 02, 1997

OTC Prod. Unit No.: 107-102104 Drilling Finished Date: July 09, 1997

1st Prod Date: August 05, 1997

Amended Completion Date: August 01, 1997

Recomplete Date: December 20, 2018

Min Gas Allowable: Yes

Drill Type: STRAIGHT HOLE

Well Name: BROOKS 2-23 Purchaser/Measurer: SCISSORTAIL

First Sales Date: 12/26/2018 OKFUSKEE 23 13N 7E Location:

NW NE SE NE 1240 FSL 2245 FWL of 1/4 SEC

Derrick Elevation: 815 Ground Elevation: 809

Operator: EGRET OPERATING COMPANY 17066

PO BOX 1871 1124 S 4TH ST

Amend Reason: RECOMPLETE

MUSKOGEE, OK 74402-1871

	Completion Type	Location Exception
Х	Single Zone	Order No
	Multiple Zone	There are no Location Exception records to display.
	Commingled	

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement											
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT				
SURFACE	8 5/8	24		460		275	SURFACE				
PRODUCTION	5 1/2	14	K	3475		225	2650				

Liner											
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth Bottom Depth				
There are no Liner records to display.											

Total Depth: 3692

Packer						
Depth	Brand & Type					
3008	ARROW SL SHR					

PI	ug
Depth	Plug Type
3150	CIBP

Initial Test Data	

March 20, 2019 1 of 2

Test Date	Formation	on Oil Oil-Grav BBL/Day (API)		Gas Gas-Oil Ratio Water MCF/Day Cu FT/BBL BBL/Day			Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Dec 26, 2018	2018 RED FORK			12			FLOWING	860	2	10
		Con	npletion and	Test Data b	y Producing F	ormation				
	Formation Name: RED F	ORK		Code: 404RDFK Class: GAS						
	Spacing Orders				Perforated In					
Orde	r No Uı	nit Size		From			о	7		
UNSP	ACED			3042 3050						
	Acid Volumes				Fracture Tre					
	800 GALLONS 7.5% HCL	-		NONE						
			nn -					-		

Formation	Тор
RED FORK	3041

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

ORIGINALLY A DUTCHER WELL AT 3,579' - 3,598'. SET CIBP @ 3,150'. RECOMPLETED IN RED FORK.

FOR COMMISSION USE ONLY

1142050

Status: Accepted

March 20, 2019 2 of 2

A record of the formations delled the										
A record of the formations drilled traolign, and pertinent remark	ks are presented on the	reverse. I declai	e that I have kn	owledge of the contents of	this report and am authori	zed by my organization				
A record of the formations drilled through, and pertinent remarks are presented on the reverse. I declare that I have knowledge of the contents of this report and am authorized by my organization to make this report which was freed by me or under my supervision and direction, with the data and facts stated herein to be true, correct, and complete to the best of my knowledge and belief.										
lan Hal		Kurt Rob			1/30/2019	918-687-8665				
partition				1	170072010	010 001 0000				
		NAME (PRINT	OR TYPE)		DATE	PHONE NUMBER				
			o		BATE	THORE NOWIDER				
P.O. Box 1871 lus	skogee, OK 744	10		kı	urt@egretoperatin	g.com				
ADDRESS	CITY	OTATE	710	***************************************						
ADDITEGG	CITY	STATE	ZIP		EMAIL ADDRESS					

FLOW TUBING PRESSURE

10 psi

PLEASE TYPE OR USE BLACK INK ONLY FORMATION RECORD

Give formation names and tops, if available, or descriptions and thickness of for drilled through. Show intervals cored or drillstem tested.						scriptions and thicking ested.	ness of formations		LEASE NA	AME		WELL NO		
NAMES (TOP				FC	R COMMISSIO	N USE ONLY	
									ITD on file		res No			
Red F	ork						3,041							
							0,011		APPROVE	ED [DISAPPROVED	2) Reject Cod	les	

									Were one	n hole logs rur	12 Ves	no		
										log was run		no		
										encountered?	yes	no at	what depths?	
									Was H₂S €	encountered?	yes	no at	what depths?	
									Were unus	sual drilling cir fly explain bel	cumstances encountered	1?	y	/esno
									J., 700, 2.110	ny explain sel				
Other rem	narke:													
Julei Tell	iiai ks.	Ori	gina	lly a	Dutcher v	vell at 3579-9	8' . Set CIBF	0 3	150'. Recom	pleted in	Red Fork.			
					-									
		640	Acres	T		BOTTOM	HOLE LOCATION	FOR DI	RECTIONAL HO	LE				
			-			SEC	TWP	RGE		COUNTY				
_						Spot Loca					Feet From 1/4 Sec Lin	nes FS		FWL
						Measured	1/4 Total Depth	1/4	1/4 True Vertical Dep		BHL From Lease, Un			1 ***
						POTTOM	HOLE LOCATION	EOD U	ODIZONTAL HOL	E. // ATEDA	1.6)			
								rok n	DRIZONTAL HOL	LE: (LATERA	LSJ			
-		+				SEC SEC	TWP	RGE		COUNTY		stantion de final action for the additional action and action and action		Commence of the Commence of th
		-	-	+		Spot Local	tion				I= .=	1		1
						Depth of	1/4	1/4	1/4 Radius of Turn	1	Feet From 1/4 Sec List Direction	nes FS		FWL
					d, attach a formation.	Deviation	Total Depth			41.		Lei	ngth	
		-		-		lvieasureu	тотат Берті		True Vertical Dep	otn	BHL From Lease, Uni	t, or Property Li	ine:	
irection m lease note	e, the ho	rizontal o	drainhol	e and it	ts end					NAN Association associate their general life was discussed as a con-				
oint must b			the bou	ındaries	of the	LATERAL SEC	#2	RGE	T	COUNTY				
)irection	_		re rea	uired	tor all	Spot Local		11.02						
rainhole		direct	ional				1/4	1/4	1/4	1.	Feet From 1/4 Sec Lir	ies FS	SL.	FWL
		640	Acres			Depth of Deviation			Radius of Turn		Direction	Tot Ler	tal ngth	Acceptance and a second a second and a second a second and a second and a second and a second and a second an
							Total Depth		True Vertical Dep	oth	BHL From Lease, Uni			
	-		_											
						LATERAL								
						SEC	TWP	RGE	_	COUNTY				
					-	Spot Locat	ion 1/4	1/4	1/4	1/	Feet From 1/4 Sec Lir	es FS	L	FWL
						Depth of	,,,,		Radius of Turn	1/	Direction	Tot		
+						Deviation Measured	Total Depth		True Vertical Dep	th	BHL From Lease, Uni		ngth ne:	
	-	+												
	1	1		1										

U16EZ

1016EZ

Form 1002A

Rev. 2009

SCANNET