Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35051241890000 Completion Report Spud Date: September 23, 2017

OTC Prod. Unit No.: 051-223322-0-0000 Drilling Finished Date: December 16, 2017

1st Prod Date: February 17, 2018

Completion Date: February 17, 2018

Drill Type: HORIZONTAL HOLE

Well Name: JO 26-35-10-6 1XH Purchaser/Measurer: COFFEYVILLE

Location: GRADY 26 10N 6W

SE NW NE NE

374 FNL 810 FEL of 1/4 SEC

Latitude: 35.31874 Longitude: -97.79728 Derrick Elevation: 1270 Ground Elevation: 1251

Operator: ROAN RESOURCES LLC 24127

14701 HERTZ QUAIL SPRINGS PKWY OKLAHOMA CITY, OK 73134-2641

	Completion Type
Х	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
688123	

Increased Density
Order No
668808

First Sales Date: 2/17/18

Casing and Cement									
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT		
SURFACE	9 5/8	40	L-80	1464		460	SURFACE		
PRODUCTION	5 1/2	23	P-110	20205		3706	7490		

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
			There are	no Liner record	ds to displa	ay.		

Total Depth: 20205

Packer					
Depth	Brand & Type				
There are no Packer records to display.					

Plug				
Depth	Plug Type			
20105	CIBP			

	Initial Test Data									
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Feb 24, 2018	MISSISSIPPIAN	294	51	2754	9367	2686	FLOWING	1550	26/128	1390

December 20, 2019 1 of 2

Completion and Test Data by Producing Formation

Formation Name: MISSISSIPPIAN

Code: 359MSSP

Class: OIL

Spacing Orders				
Order No	Unit Size			
256715	640			

Perforated Intervals				
From To				
10046	20101			

Acid Volumes	
29,666 GAL HCL ACID	

Fracture Treatments	
523,082 BBL FLUID	
20,105,835 LBS PROPPANT	

Formation	Тор
MISSISSIPPIAN	9562

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

OCC - OPERATOR LEGAL REP TO AMEND LE AND MU ORDERS AND ASSOCIATED EXHIBITS TO SHOW CORRECT SHL FOOTAGES FROM INCORRECT 374 FSL TO THE CORRECT 374 FNL

Lateral Holes

Sec: 35 TWP: 10N RGE: 6W County: GRADY

SW SE SE SE

165 FSL 384 FEL of 1/4 SEC

Depth of Deviation: 9500 Radius of Turn: 414 Direction: 177 Total Length: 10055

Measured Total Depth: 20205 True Vertical Depth: 10071 End Pt. Location From Release, Unit or Property Line: 165

FOR COMMISSION USE ONLY

1144385

Status: Accepted

December 20, 2019 2 of 2