Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

OTC Prod. Unit No.: Drilling Finished Date: August 29, 2014

1st Prod Date:

First Sales Date:

Amended

Amend Reason: MIT FAILED FIXED TUBING LEAK, RESET PKR RETURN TO INJ

Completion Date: September 19, 2014

Recomplete Date: November 02, 2020

Drill Type: STRAIGHT HOLE

SERVICE WELL

Well Name: WOODWORTH W-18I Purchaser/Measurer:

Location: STEPHENS 11 3S 5W SW SW SE SE

50 FSL 1270 FEL of 1/4 SEC

Latitude: 34.30388889 Longitude: -97.68916667 Derrick Elevation: 0 Ground Elevation: 952

Operator: BANNER OIL & GAS LLC 22792

10011 S PENNSYLVANIA AVE OKLAHOMA CITY, OK 73159-6905

Completion Type							
Х	Single Zone						
Multiple Zone							
	Commingled						

Location Exception						
Order No						
There are no Location Exception records to display.						

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement								
Type Size Weight Grade Feet PSI SAX Top of CN							Top of CMT	
PRODUCTION	4 1/2	11.6	J-55	1122		250	SURFACE	

Liner								
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 1200

Packer						
Depth	Brand & Type					
905	AD-1 TENSION					

Plug							
Depth Plug Type							
There are no Plug records to display.							

Initial Test Data

December 02, 2020 1 of 2

		BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
		ļ	There are n	o Initial Data	records to disp	lay.	ļ.	!		ļ
		Con	npletion and	Test Data b	y Producing F	ormation				
Fc	ormation Name: LOCO			Code: 40	5LOCO	С	lass: INJ			
	Spacing Orders				Perforated In	ntervals				
Order No	Ui	nit Size		From To				╗		
N/A		N/A		944 959			\neg			
1037 1052										
	Acid Volumes				Fracture Trea	atments				
There are no Acid Volume records to display.			$\neg \mid \vdash_{T}$	here are no	Fracture Treatm	nents record	s to display.			

Formation	Тор
LOCO	930

Were open hole logs run? Yes Date last log run: August 28, 2014

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

WELL FAILED MIT, ON 11/2/2020 RELEASED AD-1 TENSION PACKER, TOOH FOUND TUBING LEAK ON 3 JOINTS. REPLACED 3 JOINTS OF 2 3/8 TUBING. REDRES 4 1/2 X 2 3/8 AD-1 TENSION PACKER. TIH AND SET PACKER AT 905' PRESSURE TEST CASING TO 300#, HELD.

OCC - UIC PERMIT NUMBER 1502870056

OCC - SPACING NOT AVAILABLE INJECTION WELL

OCC - CBL RUN 9/3/2014 SUBMITTED TO OCC AS PER OCC REQUEST 9/3/2014

FOR COMMISSION USE ONLY

1145736

Status: Accepted

December 02, 2020 2 of 2