Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

Spud Date: September 14, 2004
Drilling Finished Date: September 19, 2004
1st Prod Date: October 08, 2004
Completion Date: October 06, 2004
Recomplete Date: May 03, 2021
Purchaser/Measurer:

Location: STEPHENS 34 1S 5W SW NE NE SE 2147 FSL 2192 FWL of 1/4 SEC Latitude: 34.4256728 Longitude: -97.7034227 Derrick Elevation: 1160 Ground Elevation: 1156

Operator: CITATION OIL & GAS CORPORATION 14156

14077 CUTTEN RD HOUSTON, TX 77069-2212

	Completion Type	Location Exception	Increased Density
Х	Single Zone	Order No	Order No
	Multiple Zone	There are no Location Exception records to display.	There are no Increased Density records to display.
	Commingled		

				C	asing and Cen	nent				
٦	Гуре		Size	Weight	Grade	Fe	et	PSI	SAX	Top of CMT
PRO	DUCTION		5 1/2	17	J55	11	94	1000	210	SURFACE
					Liner					
Туре	Size	Weigh	t	Grade	Length	PSI	SAX	Тор	Depth	Bottom Depth
			I	There are	no Liner record	ls to displ	ay.			1

First Sales Date:

Total Depth: 1200

Pac	ker		Р	lug
Depth	Brand & Type	Depth		Plug Type
There are no Packe	r records to display.	The	ere are no Plug	records to display.

				Initial Tes	t Data					
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
May 06, 2021	PERMIAN	0.25					PUMPING			

	Completion	and Test Data by Producing Fe	ormation
Formation Na	ame: PERMIAN	Code: 459PRMN	Class: OIL
Spacing	Orders	Perforated Ir	ntervals
Order No	Unit Size	From	То
There are no Spacing O	rder records to display.	339	1103
Acid Vo	olumes	Fracture Trea	atments
NO ADDITIONAI	L TREATMENT	NO ADDITIONAL	TREATMENT
Formation PERMIAN	Тор	Were open hole k 339 Date last log run:	-

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

OCC - PERMIAN IS UNSPACED

OCC - NO FIRST SALES DATE OR PURCHASER AT THE TIME OF THIS DOCUMENTS SUBMITTAL

OPERATOR - 1/3 (PIN END) OF 21ST JOINT HAD SEVERAL HOLES AND WAS SEVERELY PITTED W/ HEAVY SCALE DEPOSIT, 27/8" COLLAR LOOKING UP @ APPROX. 749.90' PBTD @ 1192' ORIGINAL EOT 1101 (35 JTS.) 21 JOINT TALLY 658.90'. 3/4" ROD BODY SHOULD BE ~ 39' BELOW TOP OF TUBING FISH STILL INSIDE TUBING. 16 RODS AND 2 1/4" PLUNGER LEFT IN TUBING. 14 JTS 2 7/8" TBG. AND PUMP BRL. LEFT IN WELL. SECURE WELL SDFN. SET PUMP , PUT BACK INTO PRODUCTION

FOR COMMISSION USE ONLY

Status: Accepted

1147531