Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35029214090000 Completion Report Spud Date: September 25, 2021

OTC Prod. Unit No.: 029-227671-0-0000 Drilling Finished Date: January 06, 2022

1st Prod Date: March 06, 2022

Completion Date: March 05, 2022

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: DON 2H-13 Purchaser/Measurer: ATOKA MIDSTREAM

Location: COAL 12 1N 9E First Sales Date: 03/06/2022

NE SW SE SE 600 FSL 765 FEL of 1/4 SEC

Latitude: 34.565237 Longitude: -96.304088
Derrick Elevation: 707 Ground Elevation: 682

Operator: PABLO ENERGY II LLC 21896

PO BOX 2945

801 S FILLMORE AVE STE 130 AMARILLO, TX 79105-2945

Completion Type					
Х	Single Zone				
	Multiple Zone				
	Commingled				

Location Exception
Order No
723172

Increased Density
Order No
720389

Casing and Cement									
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT		
SURFACE	9 5/8	40	J-55	247	565	200	SURFACE		
PRODUCTION	5 1/2	17	P110	11895	1245	1400	6010		

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 11906

Packer					
Depth	Brand & Type				
There are no Packer records to display.					

Plug					
Depth	Plug Type				
There are no Plug records to display.					

Initial Test Data

May 23, 2022 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Mar 08, 2022	WOODFORD	20	55	2617	130850	407	FLOWING	370	64/64	260

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: GAS

Spacing Orders						
Order No	Unit Size					
559063	640					

Perforated Intervals					
From	То				
7500	11803				

Acid Volumes 28,196 GALLONS

Fracture Treatments

136,388 BARRELS TREATED WATER
4,255,200 POUNDS SAND

Formation	Тор
WOODFORD	7008

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? Yes Explanation: THIS WELL HAS TWO SIDE TRACKS IN THE WELLBORE THAT WERE CEMENTED AND DRILLED AROUND.

Other Remarks

OCC - MOVED OFF LOCATION DRILLED ANOTHER WELL CAME BACK TO THIS WELL AND STARTED DRILLING AGAIN 11/26/2021.

Lateral Holes

Sec: 13 TWP: 1N RGE: 9E County: COAL

SE NW SE SE

615 FSL 950 FEL of 1/4 SEC

Depth of Deviation: 6534 Radius of Turn: 765 Direction: 151 Total Length: 4075

Measured Total Depth: 11906 True Vertical Depth: 6873 End Pt. Location From Release, Unit or Property Line: 615

FOR COMMISSION USE ONLY

1148135

Status: Accepted

May 23, 2022 2 of 2