

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35141008210001

Completion Report

Spud Date: August 14, 2022

OTC Prod. Unit No.: 141-230480-0-0000

Drilling Finished Date: August 16, 2022

1st Prod Date: November 02, 2022

Amended

Completion Date: September 26, 2022

Amend Reason: RE-ENTRY

Drill Type: STRAIGHT HOLE

Well Name: GRANT 1R

Purchaser/Measurer:

Location: TILLMAN 2 3S 19W
NW SW SW NW
2263 FNL 328 FWL of 1/4 SEC
Latitude: 34.328005 Longitude: -99.165989
Derrick Elevation: 1231 Ground Elevation: 1225

First Sales Date:

Operator: AC OPERATING COMPANY LLC 23061

952 ECHO LN STE 390
HOUSTON, TX 77024-2851

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	There are no Location Exception records to display.		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	10 3/4	32 3/4		172		110	SURFACE
PRODUCTION	4 1/2	10 1/2	J-55	4727		300	4150

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 5159

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		4727	CASING SHOE

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Nov 04, 2022	STRAWN	8	37			13	PUMPING		OPEN	

Completion and Test Data by Producing Formation			
Formation Name: STRAWN		Code: 404STRN	Class: OIL
Spacing Orders		Perforated Intervals	
Order No	Unit Size	From	To
NONE		4515	4545
Acid Volumes		Fracture Treatments	
2,500 GALLONS 15% NEFE		There are no Fracture Treatments records to display.	

Formation	Top
HENDERSON	2845
CANYON	3308
STRAWN GROUP	4120
STRAWN	4788
MISSISSIPPIAN	4840

Were open hole logs run? No
Date last log run: September 23, 2022

Were unusual drilling circumstances encountered? No
Explanation:

Other Remarks
THIS WAS A RE-ENTRY OF THE GRANT 1 DRILLED IN JUNE 1954.

FOR COMMISSION USE ONLY	
Status: Accepted	1149188