

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35105412420000

Completion Report

Spud Date: January 17, 2017

OTC Prod. Unit No.: 105-218278-0-0000

Drilling Finished Date: January 18, 2017

1st Prod Date: May 01, 2019

Completion Date: May 01, 2019

Drill Type: STRAIGHT HOLE

Min Gas Allowable: Yes

Well Name: GARRETT PHASE II 38B

Purchaser/Measurer: ASCENT

Location: NOWATA 1 26N 14E
NW SW SW SE
555 FSL 185 FWL of 1/4 SEC
Derrick Elevation: 0 Ground Elevation: 0

First Sales Date: 5/7/19

Operator: ROCKY TOP ENERGY LLC 22945
PO BOX 902
701 E MODOC AVE
NOWATA, OK 74048-0902

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	There are no Location Exception records to display.		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	7	13		40		5	SURFACE
PRODUCTION	4.5	10		1231		95	SURFACE

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 1241

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
May 01, 2019	BARTLESVILLE	2				5	PUMPING			

Completion and Test Data by Producing Formation

Formation Name: BARTLESVILLE

Code: 404BRVL

Class: OIL

Spacing Orders

Order No	Unit Size
NONE	

Perforated Intervals

From	To
1166	1166

Acid Volumes

NONE

Fracture Treatments

NONE

Formation	Top
OSWEGO LIME	796
IRON POST COAL	852
BARTLESVILLE	1166

Were open hole logs run? Yes

Date last log run: February 01, 2017

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

OCC - THE OCC IS WORKING WITH THE OPERATOR TO COME IN COMPLIANCE BY PROVIDING BOTH OPEN HOLE AND CEMENT BOND LOGS AS REQUIRED BY RULE.

FOR COMMISSION USE ONLY

1143064

Status: Accepted