Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35119244350000 **Completion Report** Spud Date: February 09, 2018

OTC Prod. Unit No.: Drilling Finished Date: February 12, 2018

1st Prod Date:

First Sales Date:

Completion Date: March 15, 2018

Drill Type: STRAIGHT HOLE

Well Name: GOODING 2 Purchaser/Measurer:

PAYNE 13 19N 4E Location: E2 SE NW SE

1650 FSL 1155 FWL of 1/4 SEC

Latitude: 36.119964778 Longitude: -96.824245256 Derrick Elevation: 908 Ground Elevation: 895

TRUEVINE OPERATING LLC 22516 Operator:

PO BOX 1422 2612 ARLINGTON ST ADA, OK 74821-1422

	Completion Type
Х	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	8 5/8	32	J-55	185		130	SURFACE	
PRODUCTION	5 1/2	17	J-55	3840		155	2780	

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 3854

Packer				
Depth	Brand & Type			
There are no Packer records to display.				

Plug			
Depth	Plug Type		
3740	CIBP		

Initial Test Data

June 07, 2018 1 of 3

Test Date	Forma	tion	Oil BBL/Day	Oil-Gra (API		Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Mar 12, 2018	MISEN	NER						480	SWABBIN		NONE	
Mar 14, 2018	RED F	ORK						30	SWABBIN		NONE	
			Con	npletion	and	Test Data b	y Producing F	ormation				
Formation Name: MISENER					Code: 31	9MSNR	С	lass: DRY				
Spacing Orders				Perforated Intervals								
Orde	Order No Unit Size				From To							
UNSPACED					3777		37	'80				
	Acid V	olumes					Fracture Tre	atments				
750 GALLONS 15%					NONE	.						
	Formation N	lame: RED F	ORK			Code: 40	4RDFK	С	lass: DRY			
Spacing Orders					Perforated In	ntervals						
Orde	r No	Uı	nit Size		From		n	То		\neg		
UNSP	ACED					3409	,	34	168			

I
Acid Volumes
75 BARRELS 15%

Fracture Treatments	
NONE	

Formation	Тор
CHECKERBOARD	2748
BIG LIME	3061
OSWEGO	3127
LOWER SKINNER	3338
PINK LIME	3378
RED FORK	3428
BURGESS	3654
MISSISSIPPI	3682
WOODFORD	3737
MISENER	3777
VIOLA	3802

Were open hole logs run? Yes Date last log run: March 08, 2018

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

There are no Other Remarks.

FOR COMMISSION USE ONLY

June 07, 2018 2 of 3

Status: Accepted

June 07, 2018 3 of 3

A record of the formations drilled through, and pertinent remarks are presented on the reverse. I declare that I have knowledge of the contents of this report and am authorized by my organization to make this report, which was presented by my organization, with the data and facts stated herein to be true, correct, and complete to the best of my knowledge and belief. MIKE E. FLOWERS 4/4/2018 (580) 427-7919 SIGNATURE NAME (PRINT OR TYPE) PHONE NUMBER P.O. BOX 1422 **ADA** OK 74821 MATT@TVOPERATING.COM **ADDRESS** CITY STATE ZIP **EMAIL ADDRESS**

30

SWABBING

0

NONE

N/A

WATER-BBL/DAY

CHOKE SIZE

PUMPING OR FLOWING

INITIAL SHUT-IN PRESSURE

FLOW TUBING PRESSURE

480

SWABBING

0

NONE

N/A

PLEASE TYPE OR USE BLACK INK ONLY FORMATION RECORD


Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested

minimum and a second and a second and a second as a se	
NAMES OF FORMATIONS	TOP
CHECKERBOARD	2,748
BIG LIME	3,061
OSWEGO	3127
LOWER SKINNER	3,338
PINK LIME	3,378
RED FORK	3,428
BURGESS	3,654
MISSISSIPPI	3,682
WOODFORD	3,737
MISENER	3,777
VIOLA	3,802

EASE NAME	GOODING	WELL NO.	2

	FO	COMMISSION USE O	NLY
ITD on file YES	NO		
APPROVED DISAPP	PROVED	2) Reject Codes	
Were open hole logs run?	X_ yes	no	
Date Last log was run		3/8/2018	
Was CO ₂ encountered?	yes	X no at what dep	ths?
Was H₂S encountered?	yes	X no at what dep	ths?
Were unusual drilling circumsta If yes, briefly explain below	ances encountere	1 ? .	yes X_no

		· .	
Other remarks:			
1			



If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth.

Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.

		640	Acres		
			•		
					-
			_		
-				 	
				 -	
			L		<u></u>

BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC	TWP	RGE	COUN	ΙΥ			
Spot Loc	ation	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Measure	d Total Depth	The same of the sa	Vertical Depth		BHL From Lease, Unit, or Pr	operty Line:	

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

LATERAL #1

SEC T	VP.	RGE		COUNTY			
Spot Location		1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation			Radius of Turn		Direction	Total Length	
Measured Tot	al Depth		True Vertical De	oth	BHL From Lease, Unit, or Pr	operty Line:	

LATERAL #2

SEC	TWP	RGE		COUNTY			
Spot Loc	cation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation			Radius of Turn		Direction	Total Length	
Measure	ed Total Depth		True Vertical De	pth	BHL From Lease, Unit, or Pr	operty Line:	300000

SEC	TWP	RGE		COUNTY			
Spot Loc	ation	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation			Radius of Turn		Direction	Total Length	
Measure	d Total Depth		True Vertical De	pth	BHL From Lease, Unit, or Pr		