Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

Completion Report

Spud Date: January 09, 2017

OTC Prod. Unit No.: 051-222612-0-0000 Drilling Finished Date: May 14, 2017

1st Prod Date: December 01, 2017

Completion Date: October 07, 2017

Drill Type: HORIZONTAL HOLE

API No.: 35051240900001

Well Name: RENBARGER 2H-34 Purchaser/Measurer: ENLINK

Location: GRADY 35 9N 5W SW NW NW NW

460 FNL 240 FWL of 1/4 SEC

Latitude: 35.217008 Longitude: -97.705406 Derrick Elevation: 1313 Ground Elevation: 1280

Operator: CITIZEN ENERGY II LLC 23559

320 S BOSTON AVE STE 900 TULSA, OK 74103-3729

Completion Type			
Χ	Single Zone		
	Multiple Zone		
	Commingled		

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

First Sales Date: 12/01/2017

Casing and Cement							
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	16	55		60			SURFACE
SURFACE	9.625	40	J-55	456		223	SURFACE
INTERMEDIATE	7	29	HCP-110	9395		220	8015

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4.5	13.5	HCP-110	6238	0	581	9127	15365

Total Depth: 15440

Packer				
Depth	Brand & Type			
9093	EXPRO ASIII			

Plug					
Depth Plug Type					
There are no Plug records to display.					

Initial Test Data

June 21, 2018 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Dec 28, 2017	WOODFORD	212	44	416	1962	1538	GAS LIFT		64	147

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders				
Order No	Unit Size			
653266	640			

Perforated Intervals				
From	То			
10355	15324			

Acid Volumes
11,000 GALLONS HCL

Fracture Treatments	
514,020 LBS PROPPANT 208,711 BBLS WATER	

Formation	Тор
SYCAMORE LS	9914
KINDERHOOK	10013
WOODFORD	10111

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 34 TWP: 9N RGE: 5W County: GRADY

SW SW SE SE

56 FSL 1121 FEL of 1/4 SEC

Depth of Deviation: 9327 Radius of Turn: 875 Direction: 182 Total Length: 4952

Measured Total Depth: 15440 True Vertical Depth: 9877 End Pt. Location From Release, Unit or Property Line: 56

FOR COMMISSION USE ONLY

1138150

Status: Accepted

June 21, 2018 2 of 2