Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

OTC Prod. Unit No.: 045-222481 Drilling Finished Date: May 27, 2017

1st Prod Date: October 26, 2017

Completion Date: October 26, 2017

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: STOLLER 22 1H

Purchaser/Measurer: DCP MIDSTREAM LP

Location: ELLIS 22 19N 26W First Sales Date: 10/26/2017

SW_NE_NE_NE

410 FNL 410 FEL of 1/4 SEC

Latitude: 36.1147111 Longitude: -99.9550194 Derrick Elevation: 2521 Ground Elevation: 2502

Operator: JONES ENERGY LLC 21043

807 LAS CIMAS PKWY STE 350 AUSTIN, TX 78746-6193

Completion Type					
Х	Single Zone				
	Multiple Zone				
	Commingled				

Location Exception
Order No
664099

Increased Density					
Order No					
There are no Increased Density records to display.					

Casing and Cement									
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT		
SURFACE	9 5/8	36	J-55	773	1030	535	SURFACE		
PRODUCTION	7	26	P-100	8910	1500	400	3800		

Liner								
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4 1/2	13.5	P-110	4370	0	0	8720	13090

Total Depth: 13107

Packer					
Depth	Brand & Type				
8671	BAKER X-NIPPLE PACKER				

Plug					
Depth	Plug Type				
There are no Plug records to display.					

Initial Test Data

September 07, 2018 1 of 2

	Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
N	ov 01, 2017	CLEVELAND	426	46	134	314	601	GAS LIFT	1630	38/64	310

Completion and Test Data by Producing Formation

Formation Name: CLEVELAND

Code: 405CLVD

Class: OIL

Spacing Orders					
Order No	Unit Size				
100596	640				

Perforated Intervals				
From	То			
8966	13090			

Acid Volumes

NONE

Fracture Treatments				
FRAC W/ 1,476,734 LBS PROPPANT & 45,798 BBLS FLUID				

Formation	Тор
CLEVELAND	8780

Were open hole logs run? Yes Date last log run: May 24, 2017

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

OCC - THIS DOCUMENT IS ACCEPTED BASED ON DATA SUBMITTED, THE FINAL LOCATION EXCEPTION HAS NOT BEEN ISSUED. IT APPEARS THE HEEL AND TOE OF THE LATERAL HAVE VIOLATED THE LOCATION EXCEPTION BY BEING TOO CLOSE TO THE EAST LINE, WILL BE ADDRESSED BEFORE THE FINAL ORDER IS ISSUED. THIS IS AN OPEN HOLE COMPLETION FROM THE BOTTOM OF THE 7" CASING AT 8910' TO TERMINUS AT 13107'. THE 4 1/2" CASING IS NOT CEMENTED.

Lateral Holes

Sec: 22 TWP: 19N RGE: 26W County: ELLIS

SW SE SE SE

212 FSL 369 FEL of 1/4 SEC

Depth of Deviation: 8054 Radius of Turn: 544 Direction: 180 Total Length: 4197

Measured Total Depth: 13107 True Vertical Depth: 8793 End Pt. Location From Release, Unit or Property Line: 212

FOR COMMISSION USE ONLY

1138425

Status: Accepted

September 07, 2018 2 of 2