

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35051242110000

Completion Report

Spud Date: November 05, 2017

OTC Prod. Unit No.: 051-222943-0-0000

Drilling Finished Date: December 12, 2017

1st Prod Date: January 09, 2018

Completion Date: December 20, 2017

Drill Type: HORIZONTAL HOLE

Well Name: KAYLOR 1H-30-19

Purchaser/Measurer: ENLINK

Location: GRADY 32 10N 6W
SW NW NW NW
350 FNL 175 FWL of 1/4 SEC
Latitude: 35.30428 Longitude: -97.86491
Derrick Elevation: 1322 Ground Elevation: 1296

First Sales Date: 01/09/2018

Operator: CITIZEN ENERGY II LLC 23559

320 S BOSTON AVE STE 900
TULSA, OK 74103-3729

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	679581		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	16	55		60			SURFACE
SURFACE	9.625	40	J-55	1041		393	SURFACE
PRODUCTION	5.5	20	HCP-110	20855		3448	8100

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 21018

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
10672	AS-III	There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jan 20, 2018	WOODFORD	264	54	6184	23424	465	FLOWING		36	1475

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: GAS

Spacing Orders

Order No	Unit Size
669715	640
679967	MULTIUNIT
329092	640

Perforated Intervals

From	To
11005	20786

Acid Volumes

25,000 GALLONS HCL

Fracture Treatments

19,912,860 POUNDS OF PROPPANT; 443,543 BBLS FLUID

Formation	Top
SYCAMORE	10490
WOODFORD	10647

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 19 TWP: 10N RGE: 6W County: GRADY

SW NE NE NE

388 FNL 377 FEL of 1/4 SEC

Depth of Deviation: 10075 Radius of Turn: 259 Direction: 1 Total Length: 10536

Measured Total Depth: 21018 True Vertical Depth: 10629 End Pt. Location From Release, Unit or Property Line: 388

FOR COMMISSION USE ONLY

1138466

Status: Accepted