Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35017250610001 **Completion Report** Spud Date: September 18, 2017

OTC Prod. Unit No.: 017-223275 Drilling Finished Date: September 30, 2017

1st Prod Date: February 26, 2018

Completion Date: January 10, 2018

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

First Sales Date: 02/27/2018

Well Name: HASTA 1206 (HASTA 1206 23-1WH) 23-1MH Purchaser/Measurer: ENLINK

Location: CANADIAN 26 12N 6W

NE NW NW NW

288 FNL 420 FWL of 1/4 SEC Latitude: 35.49254 Longitude: -97.8116

Derrick Elevation: 1360 Ground Elevation: 1335

Operator: 89 ENERGY LLC 23897

> 105 N HUDSON AVE STE 650 OKLAHOMA CITY, OK 73102-4832

Completion Type				
Х	Single Zone			
	Multiple Zone			
	Commingled			

Location Exception
Order No
673266

Increased Density
Order No
N/A

Casing and Cement							
Type Size Weight Grade Feet PSI SAX Top of CM							Top of CMT
SURFACE	9 5/8	36	J-55	1037	300	660	SURFACE
PRODUCTION	7	29	P-110	8190	700	685	SURFACE

Liner								
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4 1/2	13.5	P-110	6272	1600	570	7881	14153

Total Depth: 14160

Packer				
Depth	Brand & Type			
8693	SUPERIOR AS-1			

Plug				
Depth Plug Type				
There are no Plug records to display.				

Initial Test Data

July 27, 2018 1 of 3

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Mar 24, 2018	MISSISSIPPIAN	322	48	1046	3248	465	FLOWING	1038	64	170

Completion and Test Data by Producing Formation

Formation Name: MISSISSIPPIAN

Code: 359MSSP

Class: OIL

Spacing Orders				
Order No	Unit Size			
671192	640			

Perforated Intervals				
From To				
9170	14035			

Acid Volumes

296.5 BARRELS 15% ACID

Fracture Treatments

350,939 BARRELS SLICKWATER, 28,345 BARRELS 15 POUNDS GEL, 13,580,193 POUNDS PROPPANT

Formation	Тор
BASE HEEBNER	5620
TONKAWA	6234
COTTAGE GROVE	6955
CHECKERBOARD	7395
CLEVELAND	7609
OSWEGO	8063
PRUE	8185
VERDIGRIS	8235
SKINNER	8251
PINK LIME	8350
RED FORK	8384
CHESTER	8542
MERAMEC	8615

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

OCC - THIS DOCUMENT IS ACCEPTED BASED ON THE DATA SUBMITTED THE FINAL LOCATION EXCEPTION HAS NOT BEEN ISSUED.

Lateral Holes

Sec: 23 TWP: 12N RGE: 6W County: CANADIAN

NE NE NW NW

117 FNL 1220 FWL of 1/4 SEC

Depth of Deviation: 8261 Radius of Turn: 811 Direction: 356 Total Length: 4989

Measured Total Depth: 14160 True Vertical Depth: 8712 End Pt. Location From Release, Unit or Property Line: 117

FOR COMMISSION USE ONLY

July 27, 2018 2 of 3

Status: Accepted

July 27, 2018 3 of 3

A record of the formations erifled through, and pertinent remarks are presented on the reverse. I declare that I have knowledge of the contents of this report and am authorized by my organization to make this peoply which was prepared by me or under my supervision and direction, with the data and facts stated herein to be true, correct, and complete to the best of my knowledge and belief.

Lane McPherson

4/26/2018

405-602-6997

SIGNADURE

NAME (PRINT OR TYPE)

DATE

PHONE NUMBER

105 N. Hudson Ave, Suite 650

OKC

OK

73102

Iane.mcpherson@89.energy

CHOKE SIZE

FLOW TUBING PRESSURE

64

170


PLEASE TYPE OR USE BLACK INK ONLY FORMATION RECORD

Give formation names and tops, if available, or descriptions and thickness of formations

drilled through. Show intervals cored or drillstem tested.	
NAMES OF FORMATIONS	TOP
Base Heebner	5,620
Tonkawa	6,234
Cottage Grove	6,955
Checkerboard	7,395
Cleveland	7,609
Oswego	8,063
Prue	8,185
Verdigris	8,235
Skinner	8,251
Pink Lime	8,350
Red Fork	8,384
Chester	8,542
Meramec	8,615

LEASE NAME _	Н	lasta 120	6	w	ELL NO.	23-1MH
		FO	R COMMIS	SION USE ONL	Υ	
ITD on file	YES	NO				
APPROVED	DISAPPRO	/ED	2) Reject	Codes		
Were open hole lo		yes	_X_no			
Date Last log was	run				_	
was CO2 encount	tered?	yes	X no	at what depths	?	
was H₂S encounte	ered?	yes	X no	at what depths	?	
Were unusual drill		s encountere	d?	· · · · · · · · · · · · · · · · · · ·	yes	X_no

Other remarks:		
	•	



If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.

	640 Acres								
7									

BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC 1	WP	RGE		COUNTY		-	
Spot Location	n 1/4	1/4	1/4	1/-	Feet From 1/4 Sec Lines	FSL	FWL
Measured To	tal Depth		True Vertical De	oth	BHL From Lease, Unit, or Pr	operty Line:	
	- ора		1140 1014041 20		Site From Edado, Offic, of Fr	oporty Emo.	

If yes, briefly explain below

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

LATERAL #1

SEC	23	TWP	12N	RGE	6W		COUNTY		Ca	nadia	n		
Spot L		on 1/4	NE	1/4	NW 1	1/4	NW	1/4	Feet From 1/4 Sec Lines	FNL	117	FWL	1,2210
Depth Devia			8,261		Radius of Tur	'n	811		Direction 356 23	Total Length		4,989	
Measu	ured T	otal De	pth		True Vertical	Dep	oth		BHL From Lease, Unit, or Prope	rty Line:			
		14,1	160		8	3,7	12			117			

LATERAL #2

SEC TWP	RGE	C	OUNTY			
Spot Location 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation	F	Radius of Turn		Direction	Total Length	
Measured Total Depth	Т	rue Vertical Dept	1	BHL From Lease, Unit, or Pro	operty Line:	

LAT	ERAL	#:

SEC	IWP	RGE	COUN	NTY			
Spot Locati	on 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation		Ra	idius of Turn		Direction	Total Length	
Measured	Total Depth	Tru	ue Vertical Depth		BHL From Lease, Unit, or Pro	operty Line:	, 7