Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35019227400002 **Completion Report** Spud Date: February 23, 1983

OTC Prod. Unit No.: Drilling Finished Date: March 18, 1983

1st Prod Date: May 01, 1983

Amended Completion Date: May 03, 1983 Amend Reason: UPDATE STATUS - DRY

Recomplete Date: January 11, 2018

Drill Type: STRAIGHT HOLE

Well Name: LEEMAN 1-25 Purchaser/Measurer:

Location: CARTER 25 5S 2W First Sales Date:

330 FSL 2310 FWL of 1/4 SEC

Latitude: 34.08661 Longitude: -97.362805 Derrick Elevation: 0 Ground Elevation: 897

Operator: E2 OPERATING LLC 23901

C SE SE SW

1560 E 21ST ST STE 215 TULSA, OK 74114-1345

	Completion Type
Х	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
There are no Location Exception records to display.

Increased Density					
Order No					
There are no Increased Density records to display.					

Casing and Cement										
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT			
SURFACE	9 5/8			1008		700	SURFACE			
PRODUCTION	5 1/2			8240		600	6650			

Liner										
Type Size Weight Grade Le				Length	PSI	SAX	Top Depth	Bottom Depth		
There are no Liner records to display.										

Total Depth: 8240

Packer						
Depth	Brand & Type					
6758	TENSION					

Plug					
Depth	Plug Type				
7280	CIBP				

Initial Test Data

March 29, 2018 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Grav (API)			Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
	There are no Initial Data records to display.										
		Con	npletion a	and Test D	ata b	y Producing F	ormation				
	Formation Name: DEESE Code: 404DEESS Class: DRY										
	Spacing Orders					Perforated I	ntervals				
Orde	er No U	nit Size		From To							
There are no Spacing Order records to display.				6806 7180							
	Acid Volumes Fracture Treatments										
	8,000 GALLONS 7 1/2% H	CL	There are no Fracture Treatments records to display.								
Formation	Formation Top Were open hole logs run? No										

Formation	Тор
SEE ORIGINAL 1002A	0

Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks	
There are no Other Remarks.	

FOR COMMISSION USE ONLY

1138886

Status: Accepted

March 29, 2018 2 of 2

Form 1002A

Rev. 2009

PLEASE TYPE OR USE BLACK INK ONLY FORMATION RECORD 1-25 **LEEMAN** WELL NO. Give formation names and tops, if available, or descriptions and thickness of formations LEASE NAME drilled through. Show intervals cored or drillstem tested. FOR COMMISSION USE ONLY NAMES OF FORMATIONS TOP see original 1002A NO ITD on file YES DISAPPROVED APPROVED 2) Reject Codes Were open hole logs run? _yes ___ Date Last log was run _no at what depths? Was CO₂ encountered? no at what depths? Was H₂S encountered? Were unusual drilling circumstances encountered? _yes ____no If yes, briefly explain below: Other remarks: 640 Acres BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE COUNTY SEC TWP RGE Spot Location FSL Feet From 1/4 Sec Lines 1/4 1/4 1/4 1/4 Measured Total Depth BHL From Lease, Unit, or Property Line: True Vertical Depth **BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)** LATERAL #1 SEC TWP RGE COUNTY Spot Location FWL Feet From 1/4 Sec Lines FSL 1/4 1/4 Total Direction Depth of Radius of Turn Length If more than three drainholes are proposed, attach a Deviation BHL From Lease, Unit, or Property Line: Measured Total Depth True Vertical Depth separate sheet indicating the necessary information. Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the ATERAL #2 COUNTY lease or spacing unit Directional surveys are required for all Spot Location 1/4 Feet From 1/4 Sec Lines FWI FSL drainholes and directional wells. 1/4 1/4 Total Direction 640 Acres Radius of Turn Depth of Length BHL From Lease, Unit, or Property Line: Measured Total Depth True Vertical Depth LATERAL #3 COUNTY SEC TWP RGE Spot Location **FWL** Feet From 1/4 Sec Lines FSL 1/4 1/4 1/4 Total Radius of Turn Direction Depth of Length Deviation BHL From Lease, Unit, or Property Line: Measured Total Depth True Vertical Depth