Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35051240950000 **Completion Report** Spud Date: January 13, 2017

OTC Prod. Unit No.: 051-218824-0-0000 Drilling Finished Date: February 24, 2017

1st Prod Date: May 20, 2017

Completion Date: March 30, 2017

First Sales Date: 4/13/2017

Drill Type: HORIZONTAL HOLE

Well Name: GARRARD 0805 2-1XXHW Purchaser/Measurer: ENLINK

GRADY 2 8N 5W Location:

NW NE NW NE

200 FNL 1767 FEL of 1/4 SEC Latitude: 35.20327 Longitude: -97.69401 Derrick Elevation: 1282 Ground Elevation: 1252

EAGLE EXPLORATION PRODUCTION LLC 23413 Operator:

> 6100 S YALE AVE STE 700 TULSA, OK 74136-1935

	Completion Type
Х	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
665580

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
CONDUCTOR	20			110			SURFACE	
SURFACE	9.625	40	J-55	1502		445	SURFACE	
PRODUCTION	5.5	20/23	P-110	19835		2800	1153	

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
			There are	no Liner record	ds to displa	ay.		

Total Depth: 19879

Pac	ker		
Depth Brand & Type			
There are no Packer records to display.			

PI	ug			
Depth Plug Type				
There are no Plug records to display.				

Initial Test Data

July 09, 2018 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure	
May 20, 2017	WOODFORD	81	41	90	1.1111	3276	FLOWING	1600	64	260	

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders				
Order No	Unit Size			
659405	640			
659883	640			
665581	MULTIUNIT			

Perforated Intervals			
From	То		
10200	19718		

Acid Volumes	
2181 BBLS 15% HCL	

Fracture Treatments
11,939,689 # SAND 673,122 BBLS WATER

Formation	Тор
MISSISSIPPIAN	9873
WOODFORD	10015

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 11 TWP: 8N RGE: 5W County: GRADY

SE SE SW SE

77 FSL 1625 FEL of 1/4 SEC

Depth of Deviation: 9002 Radius of Turn: 1302 Direction: 180 Total Length: 9518

Measured Total Depth: 19879 True Vertical Depth: 10195 End Pt. Location From Release, Unit or Property Line: 77

FOR COMMISSION USE ONLY

1137005

Status: Accepted

July 09, 2018 2 of 2