Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35139302200002 **Completion Report** Spud Date: April 23, 1965

OTC Prod. Unit No.: Drilling Finished Date: May 12, 1965

1st Prod Date: May 19, 1965

Amended Completion Date: May 21, 1965

Recomplete Date: December 03, 1975

Drill Type: STRAIGHT HOLE

Amend Reason: RETURN STATUS TO OIL

Well Name: POSTLE MORROW L-3 UNIT 904 Purchaser/Measurer:

Location: TEXAS 29 5N 13E CM First Sales Date:

C SE NW 660 FSL 1980 FWL of 1/4 SEC

Derrick Elevation: 3373 Ground Elevation: 3366

MERIT ENERGY COMPANY 18934 Operator:

> 13727 NOEL RD STE 1200 DALLAS, TX 75240-7312

Completion Type					
Х	Single Zone				
	Multiple Zone				
	Commingled				

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement								
Type Size Weight Grade Feet PSI SAX Top of CMT								
SURFACE	8 5/8	24	J-55	1727		700	SURFACE	
PRODUCTION	4 1/2	9.5	J-55	6250		200	5550	

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 6480

Packer				
Depth Brand & Type				
There are no Packer records to display.				

Plug					
Depth Plug Type					
There are no Plug records to display.					

	Initial Test Data									
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Dec 03, 1975	MORROW UP	13		35	2691	1	PUMPING			

July 06, 2018 1 of 2

Completion and Test Data by Producing Formation

Formation Name: MORROW UP

Code: 402MRRWU

Class: OIL

Spacing Orders					
Order No Unit Size					
128530	UNIT				

Perforated Intervals					
From To					
6142	6177				

Acid Volumes

There are no Acid Volume records to display.

Fracture Treatments
There are no Fracture Treatments records to display.

Formation	Тор
SURFACE CLAY AND SAND	0
SAND	75
RED BEDS	445
SHALE AND SHELLS	954
GYP	1025
SAND	1160
RED BEDS AND SHELLS	1365
SHALE AND SHELLS	1728
SHALE AND LIME	2305
SHALE AND SHELLS	2515
SHALE AND LIME	2945
SHALE AND SHELLS	3115
LIME	3235
LIME AND SHALE	5309
LIME	5392
LIME AND SHALE	5502
SHALE WITH SAND	6037
LIME AND SHALE	6270
SHALE AND SAND	6382

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

There are no Other Remarks.

FOR COMMISSION USE ONLY

1139741

Status: Accepted

July 06, 2018 2 of 2

NAME (PRINT OR TYPE)

75240

ZIP

TX

STATE

Dallas

CITY

SIGNATURE

13727 Noel Road, Suite 1200

ADDRESS

Form 1002A

Rev. 2009

PHONE NUMBER

kathy.mcclurkan@meritenergy.com

EMAIL ADDRESS


PLEASE TYPE OR USE BLACK INK ONLY FORMATION RECORD

Give formation	names and tops,	, if available.	or descriptions	and thickness	of formation
	Show intervals				

NAMES OF FORMATIONS	ТОР
Surface Clay & Sand	0
Sand	75
Red Bed	445
Shale & Shells	954
Gyp	1,025
Sand	1,160
Red Bed & Shells	1,365
Shale & Shells	1,728
Shale & Lime	2,305
Shale & Shells	25,515
Shale & Lime	2,945
Shale & Shells	3,115
Lime	3,235
Lime & Shale	5,309
See Remarks Below	

LEASE NAME	Pos	tle Morrov	v L-3 Ut		WELL NO.	904
		F	OR COMMIS	SSION USE O	NLY	
APPROVED	YES DISAPPI	ROVED	2) Reject	Codes		
Were open hole lo	gs run?	ye	sno			
Date Last log was		ye	sno	at what depi	ths?	
Was H₂S encounte	red?	уе	sno	at what dept	ths?	

r remarks:	Lime 5392'; Lime & Shale 5502'; Shale w/Sand 6037'; Lime & Shale 6270'; Shale & Sand 6382'



If more than three drainholes are proposed, attach a separate sheet indicating the necessary information,

Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.

640 Acres							

BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC	TWP	RGE	COUN	TY			
Spot Loca	ition 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Measured	Total Depth	Tru	e Vertical Depth	•	BHL From Lease, Unit, or Pro	perty Line:	and the second s

Were unusual drilling circumstances encountered? If yes, briefly explain below

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

LATERAL #1

SEC	TWP	RGE		COUNTY			
Spot Loc	cation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviatio			Radius of Turn		Direction	Total Length	
Measure	ed Total Depth		True Vertical De	pth	BHL From Lease, Unit, or Property Line:		

LATERAL #2

SEC	TWP	RGE		COUNTY			
Spot Loc	cation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation		(i) cini,0000 (i) cine(00) (i) street (000)	Radius of Turn	***************************************	Direction	Total Length	
Measure	ed Total Depth		True Vertical De	pth	BHL From Lease, Unit, or Pr		

LATERAL #3

SEC	TWP	RGE	cou	NTY			
Spot Locat	ion 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation		I	Radius of Turn		Direction	Total Length	£
Measured	Total Depth	True Vertical Depth BHL From Lease, Unit,		BHL From Lease, Unit, or Pr	roperty Line:		