

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35015232780000

Completion Report

Spud Date: June 03, 2017

OTC Prod. Unit No.:

Drilling Finished Date: June 14, 2017

1st Prod Date: November 04, 2017

Completion Date: November 04, 2017

Drill Type: STRAIGHT HOLE

Well Name: HALLASAN 1-5 SWD

Purchaser/Measurer:

Location: CADD0 5 12N 13W
NW NE NW NE
233 FNL 1910 FEL of 1/4 SEC
Latitude: 35.550882751 Longitude: -98.59454637
Derrick Elevation: 1599 Ground Elevation: 1569

First Sales Date:

Operator: CONTINENTAL RESOURCES INC 3186
PO BOX 269000
20 N BROADWAY AVE
OKLAHOMA CITY, OK 73126-9000

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	There are no Location Exception records to display.		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9 5/8	36	J-55	544		241	SURFACE
PRODUCTION	7	26	L-80	9026		951	2545

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 9026

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
8539	AS-1X	There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
There are no Initial Data records to display.										

Completion and Test Data by Producing Formation

Formation Name: DOUGLAS

Code: 406DGLS

Class: DISP

Spacing Orders**Order No****Unit Size**

There are no Spacing Order records to display.

Perforated Intervals**From****To**

8594

8628

8636

8652

8680

8702

Acid Volumes

12,500 GAL OF 15% HCL

Fracture Treatments

There are no Fracture Treatments records to display.

Formation**Top**

DOUGLAS

7989

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks9026' PLUG BACK TOTAL DEPTH. FLOAT SHOE 9026'.
OCC - UIC PERMIT #1802360027**FOR COMMISSION USE ONLY**

1138712

Status: Accepted