Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

Completion Report

API No.: 35137035690001

OTC Prod. Unit No.:

Amended

Amend Reason: RE-ENTRY

Drill Type: STRAIGHT HOLE

Well Name: MCKINLEY-TAYLOR (TAYLOR 2) 2

Location: STEPHENS 18 1S 5W E2 NW SW SW 990 FSL 585 FWL of 1/4 SEC Derrick Elevation: 0 Ground Elevation: 0

Operator: HARMON C E OIL INC 10266

5555 E 71ST ST STE 9300 TULSA, OK 74136-6559 Spud Date: October 13, 2017 Drilling Finished Date: October 24, 2017 1st Prod Date: March 08, 2018

Completion Date: December 21, 2017

Purchaser/Measurer:

First Sales Date:

	Completion Type	Location Exception	Increased Density	
Х	Single Zone	Order No	Order No	
	Multiple Zone	669951	There are no Increased Density records to display.	
	Commingled			

Casing and Cement Size Weight Grade Feet PSI SAX Top of CMT Туре SURFACE 10.75 110 50 SURFACE PRODUCTION 7 2712 100 Liner Weight PSI SAX Туре Size Grade Length **Top Depth Bottom Depth** LINER 5 1/2 15.35 J-55 0 400 175 SURFACE 2691

Total Depth: 2745

Pac	ker	PI	ug
Depth	Brand & Type	Depth	Plug Type
There are no Packe	r records to display.	There are no Plug	records to display.

				Initial Tes	t Data					
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Mar 07, 2018	HOXBAR	1	39			70	PUMPING			

	Com	pletion and Test Da	ata by Producing Fo	ormation	
Formation N	ame: HOXBAR	Code	e: 405HXBR	Class: OIL	
Spacing	Spacing Orders		Perforated Intervals		
Order No	Unit Size	F	From	То	
663313	20	There	are no Perf. Interval	ls records to display.	
Acid Vo	blumes		Fracture Trea	atments	
NO	NE		NONE		
ormation	Тс	р	Were open hole lo	ogs run? No	
OXBAR		2690	Date last log run:	October 23, 2017	
			Were unusual dril	ling circumstances encountered?	? No

Explanation:

Other Remarks

AS THIS LEASE WAS A "START-UP" LEASE, EVEN THOUGH THE WELL WAS COMPLETED ON OCTOBER 24, 2017, THE WELL WAS NOT COMPLETED UNTIL DECEMBER 21, 2017 BECAUSE OF GETTING A PUMPING UNIT, TANK BATTERY AND ELECTRICITY INSTALLED. THE WELL WAS PUT ON THE PUMP AND MADE NOTHING BUT WATER. THE WELL WAS PUMPED UNTIL JANUARY 16, 2018, WHEN IT WAS DECIDED TO PUMP CEMENT TO THE TOP PART OF THE OPEN HOLE - TO SHUT OFF SOME WATER. THIS PROCESS TOOK UNTIL JANUARY 29, 2018, WHEN THE WELL WAS PUT BACK TO PUMPING. AN OIL SHOW APPEARED IN LATE FEBRUARY - TESTED IN EARLY MARCH. NOTE: FLUSH JOINT (FJ) 5 1/2" CASING WAS CEMENTED INSIDE THE EXISTING 7" CASING, AND CEMENT CIRCULATED TO TOP. OCC - THIS WELL IS AN OPEN HOLE COMPLETION FROM BOTTOM OF THE 7" CASING AT 2,712' TO TOTAL DEPTH AT 2,745'.

FOR COMMISSION USE ONLY

Status: Accepted

May 25, 2018

1139077

	-01								
API 13703569	PLEASE TYPE OR USE BLAC						<u>) </u>	KCE	NINEN
NO. 137035694 OTC PROD.	NOTE Attach copy of ori		0			ION COMMISSION			
	if recompletion of	•		Post	Office Box		ł	MAR 1	4 2018
ORIGINAL X AMENDED (Reason)	REENT	RY			Rule 165:10 PLETION F		OKLAH		ORPORATION
TYPE OF DRILLING OPERATI	ION DIRECTIONAL HOLE	HORIZONTAL HOLE	SPUD	DATE	10/1	3/17		640 Acre	1221011 1221011
SERVICE WELL	reverse for bottom hole location.		DRLG	FINISHED	10/2	24/17			
COUNTY STEPH		P 1S RGE 5W	DATE	OF WELL	12/2	1/17			
EASE MC	KINLEY-TAYLOR	WELL 2			3/8	3/18			
E2 1/4 NW 1/4 SW	1/4 SW 1/4 FSL OF	990 FWL OF 585	RECO	MP DATE		w			
LEVATION Groun	1/4 SEC	1/4 SEC	- L	ongitude					
PERATOR	C. E. HARMON OIL,		C/OCC	if known)	10	266			
ADDRESS		. 71ST ST., STE 9	ERATO	R NO.	10/		•		
	TULSA	STATE	0K	ZIP	74	136			
				_				LOCATE W	ELL
X SINGLE ZONE		CASING & CEMENT (F	orm 10 SIZE	WEIGHT	GRADE	FEET	PSI	SAX	TOP OF CMT
MULTIPLE ZONE Application Date		CONDUCTOR							
COMMINGLED Application Date		SURFACE 1	0.75"			110		50	Surface
	69951	INTERMEDIATE							
NCREASED DENSITY		PRODUCTION	7"			2712		100	
		LINER 5	1/2"	15.35#	J-55	GNI 2691	400	175	SURFACE
ACKER @BRAN		_PLUG @	_TYPE	•	PLUG @	TYPE		TOTAL DEPTH	2,745
					PLUG @	TYPE	<u> </u>		
ORMATION	HOXBAR	T						· · · · · ·	
PACING & SPACING	20 ACRES/663313	669951 Loc Exc	-			<u>_</u>			
ASS: Oil, Gas, Dry, Inj, isp, Comm Disp, Svc	OIL								
	OPEN-HOLE								
RFORATED FERVALS									
CID/VOLUME	NONE					<u> </u>			
	NONE								
RACTURE TREATMENT luids/Prop Amounts)			-						
	Min Gas Allo	owable (165:10-1	7-7)			Purchaser/Measurer			
ITIAL TEST DATA	OR Oil Allowabl	e (165:10-13-3)			First	Sales Date			
ITIAL TEST DATE	3/7/2018								
IL-BBL/DAY	1		1						
IL-GRAVITY (API)	39.0								
AS-MCF/DAY	0			_///		SUBN	///////	1111	
AS-OIL RATIO CU FT/BBL	N/A			-7 F					
VATER-BBL/DAY	70			-71	5	SIIRN	ITTE	:nľ	
JMPING OR FLOWING	Pumping			-7				IJĽ	
IITIAL SHUT-IN PRESSURE	N/A		1	-'////			111111	mi.	
HOKE SIZE	N/A				/			////	
LOW TUBING PRESSURE	N/A								
to make this report, whethwas	ed through, and pertinent remark prepared by me or under my sup	ervision and direction, with i	he data	and facts stat	ed herein to	dge of the contents of o be true, correct, and	this report and an complete to the b 3/12/201	est of my kr	by my organization nowledge and belief. 18) 663-8515
SIGNAT	URE CONTRACTOR			T OR TYPE		· ·		<u>`</u>	HONE NUMBER
5555 E. 71ST S		TULSA	ok	74136		r	ehoil@sbcgl		
ADDRE	ESS	CITY S	TATE	ZIP			EMAIL ADD	RESS	

.

PLEASE TYPE OR USE BLACK INK ONL FORMATION RECORD Give formation names and tops, if available, or descriptions and this drilled through. Show intervals cored or drillstem tested.			MCKINLEY-TA	YLOR	WELL NO.	2
NAMES OF FORMATIONS	TOP		FO	R COMMISSION USE	ONLY	
HOXBAR	2,690	ITD on file	YES NO	2) Reject Codes		
• • • • • • • • • • • • • • • • • • • •		Were open hole to Date Last log was Was CO ₂ encoun Was H ₂ S encount Were unusual drill If yes, briefly expla	tered?yes ered?yes ling circumstances encounter	X no at what d	·	no
Other remarks: As this lease was a "start-up" leas	e, even though t	he well was comple		e well was not co	ompleted unti	
12/21/17 because of getting a pumping unit, ta						
water. The well was pumped until 1/16/18, who						
This process took until 1/29/18, when the well				•		

NOTE: Flush joint (FJ) 5 1/2" casing was cemented inside the existing 7" casing, and cement circulated to top.

BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE TO total depth at 2745' CC-This well is an open hole completion 640 Acres

If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.

		,	

 SEC
 TWP
 RGE
 COUNTY

 Spot Location
 1/4
 1/4
 1/4

 1/4
 1/4
 1/4
 1/4

 Measured Total Depth
 True Vertical Depth
 BHL From Lease, Unit, or Property Line:

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

SEC	TWP	RGE		COUNTY			
Spot Loc					Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviatior	1/4	1/4	1/4 Radius of Turn	1/4	Direction	Total Length	
Measure	Total Depth		True Vertical De	pth	BHL From Lease, Unit, or Pr	operty Line:	
LATERA	L #2						
	L #2	RGE		COUNTY			
SEC	TWP	RGE			Foot From 1/4 Foot Linco		
SEC	TWP	RGE	1/4		Feet From 1/4 Sec Lines	FSL	FWL
LATERA SEC Spot Loc Depth of Deviatior	TWP ation 1/4				Feet From 1/4 Sec Lines	FSL Total Length	FWL

SEC	TWP	RGE		COUNTY			
Spot Loca	1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation			Radius of Turn		Direction	Total Length	I
Measured	Total Depth		True Vertical Dep	oth	BHL From Lease, Unit, or Pr		