

Oklahoma Corporation Commission  
Oil & Gas Conservation Division  
Post Office Box 52000  
Oklahoma City, Oklahoma 73152-2000  
Rule 165: 10-3-25

Form 1002A

API No.: 35133252380001

**Completion Report**

Spud Date: February 06, 2017

OTC Prod. Unit No.:

Drilling Finished Date: February 15, 2017

1st Prod Date: March 15, 2017

Completion Date: February 22, 2017

**Drill Type: STRAIGHT HOLE**

Well Name: MOGA 1-23

Purchaser/Measurer:

Location: SEMINOLE 23 8N 6E  
C SW NE  
1980 FNL 1980 FEL of 1/4 SEC  
Derrick Elevation: 1000 Ground Elevation: 971

First Sales Date:

Operator: CIRCLE 9 RESOURCES LLC 23209  
PO BOX 249  
210 PARK AVE STE 1350  
OKLAHOMA CITY, OK 73101-0249

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
NONE

Increased Density
Order No
NONE

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	13 3/8			40		150	SURFACE
SURFACE	9 5/8			1161		450	SURFACE
PRODUCTION	7			4104		200	1200

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

**Total Depth: 4144**

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
4080	RBP

Initial Test Data
-------------------

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Mar 16, 2017	FIRST WILCOX	5	38			800	PUMPING			
Apr 28, 2017	VIOLA	9	38			800	PUMPING			

#### Completion and Test Data by Producing Formation

Formation Name: FIRST WILCOX

Code: 202WLCX1

Class: DRY

##### Spacing Orders

Order No	Unit Size
660262	160

##### Perforated Intervals

From	To
4104	4144

##### Acid Volumes

NONE
------

##### Fracture Treatments

NONE
------

Formation Name: VIOLA

Code: 202VIOL

Class: OIL

##### Spacing Orders

Order No	Unit Size
660262	160

##### Perforated Intervals

From	To
4030	4040
4050	4070

##### Acid Volumes

NONE
------

##### Fracture Treatments

NONE
------

Formation	Top
VIOLA	4024
FIRST WILCOX	4104

Were open hole logs run? Yes

Date last log run: February 15, 2017

Were unusual drilling circumstances encountered? No

Explanation:

#### Other Remarks

There are no Other Remarks.

#### FOR COMMISSION USE ONLY

1137416

Status: Accepted