

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35083357610003

Completion Report

Spud Date: October 09, 1957

OTC Prod. Unit No.: 083-33234

Drilling Finished Date: October 21, 1957

Amended

1st Prod Date: January 06, 1965

Amend Reason: SHOW WELL PRODUCING

Completion Date: October 31, 1957

Recomplete Date: October 27, 2017

Drill Type: STRAIGHT HOLE

Well Name: NAKVINDA-DAVIS 1

Purchaser/Measurer:

Location: LOGAN 16 16N 4W
C SW NW SE
1650 FSL 330 FWL of 1/4 SEC
Derrick Elevation: 1010 Ground Elevation: 1002

First Sales Date:

Operator: MIDWEST ENTERPRISES INC 6773

17980 W PRARIE GROVE RD
CASHION, OK 73016-9626

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	N/A		N/A	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	10 3/4			220		200	SURFACE
PRODUCTION	5 1/2	14 - 15.5	J-55	6654		200	5996

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4		HYD	370	0	0	6656	

Total Depth: 7026

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
6445	RBP

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Nov 02, 2017	PRUE	2		2	1000	2	PUMPING	40		

Completion and Test Data by Producing Formation			
Formation Name: PRUE		Code: 404PRUE	Class: OIL
Spacing Orders		Perforated Intervals	
Order No	Unit Size	From	To
NONE		6258	6268
Acid Volumes		Fracture Treatments	
1,500		NONE	


Formation	Top
PRUE	6258

Were open hole logs run? No
Date last log run:

Were unusual drilling circumstances encountered? No
Explanation:

Other Remarks
PERFORATED INTERVALS REPORTED ON 1002A DATED JULY 18, 2001 6,270' - 6,280', 6,686' - 6,694' WERE TESTED. PERFORATIONS OPENED AND ABANDONED.

FOR COMMISSION USE ONLY	
Status: Accepted	1139097

 SIGNATURE		JAMES M. FRANKLIN, AGENT NAME (PRINT OR TYPE)		12/15/17 405-4332 DATE PHONE NUMBER	
17980 W. PRAIRIE GROVE RD, CASHIOW, OK, 73016 ADDRESS		CITY STATE ZIP		EMAIL ADDRESS	

PLEASE TYPE OR USE BLACK INK ONLY

FORMATION RECORD

Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested.

LEASE NAME NAKVINDA - DAVIS

WELL NO. 1

NAMES OF FORMATIONS	TOP
<i>PRUE</i>	<i>6258</i>

FOR COMMISSION USE ONLY

ITD on file ☐ YES ☐ NO

APPROVED _____ DISAPPROVED _____

2) Reject Codes

Were open hole logs run? _____ yes _____ no

Date Last log was run _____

Was CO₂ encountered? _____ yes _____ no at what depths? _____

Was H₂S encountered? _____ yes _____ no at what depths? _____

Were unusual drilling circumstances encountered? _____ yes _____ no

If yes, briefly explain below

Other remarks: *PERF. INTERVALS reported on 1002A DTD 7/18/01 6270-80, 6686-94 WERE TESTED. PERFS opened and abandoned.*

640 Acres

If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth.
Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.

640 Acres

BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC	TWP	RGE	COUNTY
Spot Location	1/4	1/4	1/4
Measured Total Depth	True Vertical Depth		Feet From 1/4 Sec Lines
			FSL
			FWL
BHL From Lease, Unit, or Property Line:			

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

LATERAL #1

SEC	TWP	RGE	COUNTY
Spot Location	1/4	1/4	1/4
Depth of Deviation	Radius of Turn	Direction	Total Length
Measured Total Depth	True Vertical Depth		BHL From Lease, Unit, or Property Line:

LATERAL #2

SEC	TWP	RGE	COUNTY
Spot Location	1/4	1/4	1/4
Depth of Deviation	Radius of Turn	Direction	Total Length
Measured Total Depth	True Vertical Depth		BHL From Lease, Unit, or Property Line:

LATERAL #3

SEC	TWP	RGE	COUNTY
Spot Location	1/4	1/4	1/4
Depth of Deviation	Radius of Turn	Direction	Total Length
Measured Total Depth	True Vertical Depth		BHL From Lease, Unit, or Property Line: