Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35045236970000 Completion Report Spud Date: October 22, 2017

OTC Prod. Unit No.: 045-223053 Drilling Finished Date: December 10, 2017

1st Prod Date: February 11, 2018

Completion Date: January 21, 2018

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: TERRY 14-11 1H Purchaser/Measurer: MARKWEST

Location: ELLIS 14 18N 23W First Sales Date: 02/11/2018 SE SE SW SW

250 FSL 1110 FWL of 1/4 SEC Latitude: 36.0288 Longitude: -99.6271

Derrick Elevation: 2273 Ground Elevation: 2246

Operator: VALPOINT OPERATING LLC 23241

600 S TYLER ST STE 1701 AMARILLO, TX 79101-2353

Χ	Single Zone	
	Multiple Zone	Ther
	Commingled	

Location Exception
Order No
There are no Location Exception records to display.

Increased Density					
Order No					
There are no Increased Density records to display.					

Casing and Cement							
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	20	54	H-40	120			SURFACE
SURFACE	13 3/8	54.5	J-55	1536		1010	SURFACE
INTERMEDIATE	9 5/8	40	HCL-80	9489		860	5727
INTERMEDIATE	7	29	P-110	9842		495	6832
PRODUCTION	5 1/2	20	P-110	18758		870	2909

Liner						
Type Size Weight Grade Length PSI SAX Top Depth Bottom Depth						
There are no Liner records to display.						

Total Depth: 18758

Packer					
Depth	Brand & Type				
There are no Packer records to display.					

	Plug			
	Depth	Plug Type		
There are no Plug records to display.				

May 29, 2018 1 of 2

	Initial Test Data									
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Feb 13, 2018	OSWEGO	743	42	1356	1825	2838	FLOWING	2000	40	820

Completion and Test Data by Producing Formation

Formation Name: OSWEGO

Code: 404OSWG

Class: OIL

Spacing Orders				
Order No	Unit Size			
670973	1280			
21321112				

Perforated Intervals				
From	То			
9880	18161			

Acid Volumes

160,860 GALLONS 15% HCL

Fracture Treatments

11,159,736 GALLONS, 881,957 POUNDS 100 MESH SAND, 2,622,581 POUNDS 40/70 SAND

Formation	Тор
DOUGLAS	7284
TONKAWA	7818
COTTAGE GROVE	8379
CLEVELAND	8933
BIG LIME	9291
OSWEGO	9396

Were open hole logs run? Yes Date last log run:

Were unusual drilling circumstances encountered? Yes Explanation: OCC - OPERATOR LOST HOLE AT 9531'. SIDE TRACK STARTED AT 9303'.

Other Remarks

7" CASING IS 2ND INTERMEDIATE STRING - 6,472' - 9,842' MD. PRODUCTION CASING - 5-1/2" 20# @ 9,473' AND 4-1/2" 9,473' - 18,754' MD. FRAC COMPLETED ON FEBRUARY 1, 2018. STARTED THROUGH PRODUCTION EQUIPMENT AND FIRST SALES ON FEBRUARY 11, 2018 @ 8:30 PM. OCC - THIS WELL IS SPACED ON A 1280 ACRE UNIT COMPRISING OF SECTION 11 & 14 OF 18N-23W. THE WELL IS AT A LEGAL DISTANCE TO WHAT THE SPACING ORDER ALLOWS.

Lateral Holes

Sec: 11 TWP: 18N RGE: 23W County: ELLIS

NE SE NW NW

1770 FSL 1113 FWL of 1/4 SEC

Depth of Deviation: 8883 Radius of Turn: 1156 Direction: 6 Total Length: 8719

Measured Total Depth: 18758 True Vertical Depth: 9404 End Pt. Location From Release, Unit or Property Line: 870

FOR COMMISSION USE ONLY

1139083

Status: Accepted

May 29, 2018 2 of 2

600 S. Tyler St, Suite 1701

ADDRESS

Amarillo

CITY

TX

STATE

79101

ZIP

matt@valpointoperating.com

EMAIL ADDRESS


PLEASE TYPE OR USE BLACK INK ONLY FORMATION RECORD

	I DIGITAL RECORD
Give formation names and tops.	, if available, or descriptions and thickness of formations
drilled through. Show intervals	cored or drillstem tested.

NAMES OF FORMATIONS	TOP
Douglas	7284' (-5011'
Tonkawa	7818' (-5539'
Cottage Grove	8379' (-6106'
Cleveland	8933' (-6659'
Big Lime	9291' (-7018'
Oswego	9396' (-7123
	`

EASE NAME	WELL NO.
	FOR COMMISSION USE ONLY
ITD on file YES APPROVED DISAPPI	ROVED 2) Reject Codes
Wors open halo less x x2	V
Were open hole logs run? Date Last log was run	<u>X</u> yes <u>no</u> 12/7/2018
Was CO₂ encountered?	yes X no at what depths?
Was H ₂ S encountered?	yes X no at what depths?
Were unusual drilling circumstar	nces encountered?yesX_no


7" casing is 2nd intermediate string - 6,472' - 9,842' MD.	
Production Casing - 5-1/2" 20# @ 9,473' and 4-1/2" 9,473'-18,754' MD.	
Frac completed on 2/1/2018. Started through production equipment and first sales on 2/11/2018 @8:30 p	m.
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,



If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.



BOTTOM HOLE LOCATION FOR	DIRECTIONAL HOLE LOST	note (see Si	11 veys)	
SEC 14 TWP 18N RO	E 23W COUNTY	Ellis		
Spot Location AE 1/4 SE 1/4	14 SW 1/4 SW 1/4	Fest From 1/4 Sec Lines	FSL 586	FW1994
Measured Total Depth	True Vertical Depth	BHL From Lease, Unit, or Pro	perty Line:	
9531	9408	58	36	

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

LATERAL #1 SEC 11 TWP COUNTY 18N 23W Ellis Spot Location NE 1/4 1/4 Feet From 1/4 Sec Lines FSL 1770' FWL 1113' SE 1/4 NW 1/4 NW Depth of Radius of Turn Direction Total 8,883' 1,156' 6.1 Deviation O, Measured Total Depth 8,719 BHL From Lease, Unit, or Property Line: True Vertical Depth 18,758 9,404' 870'

LATERAL #2				
SEC 14 TWP 18N RG	E 23W COUNTY	Ellis		
Spot Location SE 1/4		1/4 Feet From 1/4 Sec Lines	FSL 586	FWL 994
Depth of Deviation	Radius of Turn 123	Direction 4	Total Length	
Measured Total Depth	True Vertical Depth	BHL From Lease, Unit, or Pre	operty Line:	
9531	9408		586	

SEC	TWP	RGE		COUNTY			
Spot Loc	ation						—
	1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation	n		Radius of Turn		Direction	Total Length	
Measured Total Depth True Vertical Depth		BHL From Lease, Unit, or Property Line:					