

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35087220830000

Completion Report

Spud Date: August 19, 2017

OTC Prod. Unit No.: 087222337

Drilling Finished Date: September 11, 2017

1st Prod Date: October 25, 2017

Completion Date: October 04, 2017

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: GUINNESS 1-32-5-WXH

Purchaser/Measurer: ONEOK

Location: MCCLAIN 29 6N 4W
SE SW SW SW
200 FSL 400 FWL of 1/4 SEC
Latitude: 34.957482 Longitude: -97.651478
Derrick Elevation: 1215 Ground Elevation: 1189

First Sales Date: 10/27/17

Operator: CASILLAS OPERATING LLC 23838

401 S BOSTON AVE STE 2400
TULSA, OK 74103-4060

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	679506		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40.00	J-55	1517		375	SURFACE
PRODUCTION	5.50	20.00	P-110	21529		2140	4785

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 21529

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Nov 13, 2017	WOODFORD	244	48	402	1648	1967	FLOWING		20/64	190

Completion and Test Data by Producing Formation	
Formation Name: WOODFORD	Code: 319WDFD
Class: OIL	

Spacing Orders	
Order No	Unit Size
664259	640
665720	640
679968	MULTIUNIT

Perforated Intervals	
From	To
11808	21460

Acid Volumes	
410 BBLS ACID	

Fracture Treatments	
23,460,820 LBS PROP & 612,991 BBLS	

Formation	Top
WOODFORD	11475

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks
There are no Other Remarks.

Lateral Holes
Sec: 5 TWP: 5N RGE: 4W County: MCCLAIN SE NW SW SW 700 FSL 408 FWL of 1/4 SEC Depth of Deviation: 10965 Radius of Turn: 602 Direction: 180 Total Length: 9618 Measured Total Depth: 21529 True Vertical Depth: 11586 End Pt. Location From Release, Unit or Property Line: 700

FOR COMMISSION USE ONLY	
Status: Accepted	1137947