Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35073249620001 **Completion Report** Spud Date: August 07, 2014

OTC Prod. Unit No.: 073-214488 Drilling Finished Date: August 31, 2014

1st Prod Date: September 30, 2014

Completion Date: September 23, 2014

Amend Reason: CORRECT PERFORATION DEPTHS **HORIZONTAL HOLE**

Well Name: E HENNESSEY UNIT 224H-O Purchaser/Measurer:

KINGFISHER 6 18N 6W Location: First Sales Date:

NE NE NW NE

165 FNL 1270 FWL of 1/4 SEC

Latitude: 36.0726308 Longitude: -97.876187333 Derrick Elevation: 1149 Ground Elevation: 1134

HINKLE OIL & GAS INC 21639 Operator:

> 5600 N MAY AVE STE 295 **OKLAHOMA CITY, OK 73112-4275**

	Completion Type
Х	Single Zone
	Multiple Zone
	Commingled

Amended

Drill Type:

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement									
Type Size Weight Grade Feet PSI SAX Top of CM									
CONDUCTOR	20			65		10	SURFACE		
SURFACE	9 5/8	36	LSSTC	442		350	SURFACE		
PRODUCTION	7	26	P-110	6677		175	5840		

Liner								
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4 1/2	11.6	P-110	3907	0	341	6552	10459

Total Depth: 10462

Packer					
Depth	Brand & Type				
There are no Packer records to display.					

Plug						
Depth Plug Type						
There are no Plug records to display.						

Initial Test Data

February 09, 2018 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Oct 05, 2014	OSWEGO	80	41.3	110	1375	295	FLOWING		OPEN	100

Completion and Test Data by Producing Formation

Formation Name: OSWEGO

Code: 404OSWG

Class: OIL

Spacing Orders					
Order No	Unit Size				
61709	UNIT				

Perforated Intervals				
From To				
6552	10232			

Acid Volumes

4,000 GALLONS 15% NEFE HCL, 162,204 GALLONS 15% NEFE HCL Fracture Treatments

58,452 BARRELS SLICK WATER, 636,739 POUNDS
30/50 SAND

Formation	Тор
CHECKERBOARD	6099
BIG LIME	6300
2ND OSWEGO	6362
3RD OSWEGO	6401
4TH OSWEGO	6435

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 6 TWP: 18N RGE: 6W County: KINGFISHER

SE NE SW SE

810 FSL 1271 FWL of 1/4 SEC

Depth of Deviation: 5750 Radius of Turn: 1188 Direction: 180 Total Length: 3524

Measured Total Depth: 10462 True Vertical Depth: 6429 End Pt. Location From Release, Unit or Property Line: 810

FOR COMMISSION USE ONLY

1138530

Status: Accepted

February 09, 2018 2 of 2

Form 1002A

Rev. 2009

A record of the formations drilled through, and pertinent remarks are presented on the reverse. I declare that I have knowledge of the contents of this report and am authorized by my organization								
to make this report, which was prepared by me or under my supervision and direction, with the data and facts stated herein to be true, correct, and complete to the best of my knowledge and belief.								
(L A.M. SA	,				1/5/2018			
13 Mine	Bruce A. Hinkle					405-848-0924		
	·							
SIGNATURE	NAME (PRINT OR TYPE)				DATE	PHONE NUMBER		
5000 N N A 0 11 00-		- '						
5600 N. May Avenue, Suite 295	Oklahoma City OK 73112				Laurahinkle@hoagi.com			
ADDRESS	CITY STATE ZIP				EMAIL ADDRESS			
						· · · · · · · · · · · · · · · · · · ·		

100

FLOW TUBING PRESSURE

PLEASE TYPE OR USE BLACK INK ONLY

FORMATION RECORD

Give formation	names and tops.	if available.	or descriptions	and thickness of formations
	Show intervals of			

NAMES OF FORMATIONS	TOP
	·
Checkerboard	6099'
Big Lime	6300'
2nd Oswego	6362'
3rd Oswego	6401'
4th Oswego	6435'

LEASE NAME	East Hennessey Unit	WELL NO.	224H-O
	FOR COMMISSION USE	ONLY	


ŀ		FOI	R COMMISSION USE ONLY
ITD on file	YES	NO	
APPROVED	DISAPPR	OVED	2) Reject Codes
Were open ho		yes	_X_no

X no at what depths?

Other remarks:	•		

Was CO₂ encountered? Was H₂S encountered?


If yes, briefly explain below



If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.



BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC TWP	RGE	COUNT	Υ			
Spot Location	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Measured Total Depti	True	Vertical Depth	1	BHL From Lease, Unit, or Pr	operty Line:	

Were unusual drilling circumstances encountered?

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

SEC 6 TWP COUNTY Kingfisher 18N 6W 1271 NESW Feet From 1/4 Sec Lines Spot Location
S1 1/4
Depth of FSL 180'810 FWL 1320" SE Direction /BO South Total Radius of Turn 3524' 1188' 5750' BHL From Lease, Unit, or Property Line: Deviation True Vertical Depth Measured Total Depth 180 810 6429' 10,462

SEC	TWP	RGE	COUNT	Y			
Spot Loca	ation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation			us of Turn		Direction	Total Length	
Measured	d Total Depth	True	Vertical Depth		BHL From Lease, Unit, or Pr	operty Line:	

SEC	TWP	RGE		COUNTY			
Spot Loc	cation	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviatio	F		Radius of Turn		Direction	Total Length	
Measured Total Depth			True Vertical Dep	oth	BHL From Lease, Unit, or Pro	operty Line:	