Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35133228510001 Completion Report Spud Date: September 06, 1984

OTC Prod. Unit No.: Drilling Finished Date: September 15, 1984

1st Prod Date:

First Sales Date:

Amended

Amend Reason: WELL REPAIRS - RAN NEW 5 1/2" CASING

Completion Date: October 01, 1984

Recomplete Date: August 29, 2019

Drill Type: STRAIGHT HOLE

SERVICE WELL

Well Name: MARSHALL 1-A Purchaser/Measurer:

Location: SEMINOLE 36 8N 6E

NW SE NW NW

1815 FSL 825 FWL of 1/4 SEC

Latitude: 35.128052 Longitude: -96.632025 Derrick Elevation: 926 Ground Elevation: 916

Operator: LAPETCO INC 12358

2745 DALLAS PKWY STE 455 PLANO, TX 75093-8749

Completion Type							
Х	Single Zone						
	Multiple Zone						
	Commingled						

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement							
Type Size Weight Grade Feet PSI SAX Top of CMT							
SURFACE	10 3/4	40.5	J-55	122	1000	125	SURFACE
PRODUCTION	7	17	J-55	4357	3000	80	3500

Liner								
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	5 1/2	17	J-55	0	0	220	SURFACE	4198

Total Depth: 4400

Packer						
Depth	Brand & Type					
4180	ARROW TENSION					

Plug						
Depth Plug Type						
There are no Plug records to display.						

Initial Test Data

October 23, 2019 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure	
•	There are no Initial Data records to display.										
		Con	npletion and	Test Data b	y Producing F	ormation					
	Formation Name: 1ST V	VILCOX		Code: 20	2WLCX1	C	lass: DISP				
Spacing Orders Perforated Int				ntervals							
Order No Unit Size				From To							
There are no Spacing Order records to display.				4224	1	42	234				
Acid Volumes					Fracture Tre	atments					
500 GALLONS					NONE			7			

Formation	Тор
CROMWELL SAND	3230
VIOLA LIMESTONE	4090
SIMPSON	4176
1ST WILCOX	4210

Were open hole logs run? Yes Date last log run: September 15, 1984

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

WELL REPAIRS FOR MIT. RAN 101 JTS 5.5 CASING TO 4,198'. CEMENTED TO SURFACE. RAN 4,180' 2 3/8 TUBING AND SET PACKER. TESTED WELL WITH OCC. WELL PASSED MIT SEPTEMBER 3, 2019. ORDER NUMBER 375179. OCC - A D-V TOOL WAS SET IN THE 7" CASING AT 1009' AND 280 SACKS OF CEMENT WAS USED TO LIFT CEMENT TO SURFACE.

FOR COMMISSION USE ONLY

1143791

Status: Accepted

October 23, 2019 2 of 2

Rev. 2009

PLEASE TYPE OR USE BLACK INK ONLY


FORMATION RECORD

Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals covert or drillstern tested

dniled through. Show intervals cored or dnilstem tested.						
NAMES OF FORMATIONS	ТОР					
Cromwell Sand	3,230					
Viola Limestone	4,090					
Simpson	4176					
1st Wilcox	4,210					

LEASE NAME	WELL NO				
	FOI	R COMMIS	SION USE ONLY		
ITD on file YES APPROVED DISAPPROV	□□NO ÆD	2) Reject (Codes		
Were open hole logs run?		no			
Date Last log was run		9/15/1	984	_	
Was CO₂ encountered? Was H₂S encountered?			at what depths?		
Were unusual drilling circumstances If yes, briefly explain below				yes X no	


Other remarks:	Well repairs for MIT. Ran 101 Jts 5.5	casing to 4198.	Cemented to surface.	Ran 4180' 2 3/8 tubing and set packer.
Tested well v	with OCC. Well Passed MIT 9/3/2019.	ORDER	375179	



If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.



BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC	TWP	RGE	COUNT	Y			
Spot Loca	ation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL.	FWL
Measured	Total Depth	True	Vertical Depth		BHL From Lease, Unit, or Pro	operty Line:	

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

SEC	TWP	RGE		COUNTY			
Spot Loc	cation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of		1/4	Radius of Turn		Direction	Total	Island
Deviatio	n					Length	
Measure	ed Total Depth		True Vertical Dept	h	BHL From Lease, Unit, or Pro	perty Line:	

SEC	TWP	RGE	co	UNTY			
Spot Loc	ation	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation		<u> </u>	Radius of Turn		Direction	Total Length	N. C.
Measure	d Total Depth		True Vertical Depth		BHL From Lease, Unit, or Pro	operty Line:	

SEC	TWP	RGE		COUNTY			
Spot Loc	cation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation			Radius of Turn		Direction	Total Length	<u> </u>
Measured Total Depth True Vertical Depth			oth	BHL From Lease, Unit, or Property Line:			