

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35133253590000

Completion Report

Spud Date: April 20, 2021

OTC Prod. Unit No.: 133-227204-0-0000

Drilling Finished Date: April 30, 2021

1st Prod Date: June 10, 2021

Completion Date: June 02, 2021

Drill Type: DIRECTIONAL HOLE

Well Name: ZELLER 1-35

Purchaser/Measurer: CVR

Location: SEMINOLE 35 8N 5E
SW NW SE SW
769 FSL 1594 FWL of 1/4 SEC
Latitude: 35.11786951 Longitude: -96.75232686
Derrick Elevation: 0 Ground Elevation: 0

First Sales Date:

Operator: REACH OIL AND GAS COMPANY INC 24558

6301 WATERFORD BLVD STE 120
OKLAHOMA CITY, OK 73118-1100

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	There are no Location Exception records to display.		There are no Increased Density records to display.	
	Commingle				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8 5/8	24	J-55	874		450	SURFACE
PRODUCTION	5 1/2"	15.5	J-55	4654		290	2800

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 4860

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jun 10, 2021	HUNTON	8	40				PUMPING			

Completion and Test Data by Producing Formation			
Formation Name: HUNTON		Code: 269HNTN	Class: OIL
Spacing Orders		Perforated Intervals	
Order No	Unit Size	From	To
717746	160	4452	4461
Acid Volumes		Fracture Treatments	
1500 GALS 15% HCL		There are no Fracture Treatments records to display.	

Formation	Top
CALVIN	2917
SENORA	3334
EARLSBORO	3472
BARTLESVILLE	3716
WOODFORD	4319
HUNTON	4452
VIOLA	4602
SIMPSON DOLOMITE	4712
1ST WILCOX	4748
2ND WILCOX	4860

Were open hole logs run? Yes

Date last log run: April 27, 2021

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks
OCC - SPACING ORDER 717746 CREATED AN IRREGULAR UNIT COMPRISING OF SE SW & SW SE SECTION 35-8N-5E AND NW NE & NE NW SECTION 2-7N-5E.

Bottom Holes
<p>Sec: 35 TWP: 8N RGE: 5E County: SEMINOLE</p> <p>SW SE SE SW</p> <p>36 FSL 2232 FWL of 1/4 SEC</p> <p>Depth of Deviation: 0 Radius of Turn: 0 Direction: 0 Total Length: 0</p> <p>Measured Total Depth: 4860 True Vertical Depth: 4730 End Pt. Location From Release, Unit or Property Line: 912</p>

FOR COMMISSION USE ONLY	
Status: Accepted	1146628