

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35049253390000

Completion Report

Spud Date: September 18, 2021

OTC Prod. Unit No.: 049-227527-0-0000

Drilling Finished Date: October 07, 2021

1st Prod Date: February 02, 2022

Completion Date: February 08, 2022

Drill Type: DIRECTIONAL HOLE

Well Name: LLOYD 1

Purchaser/Measurer:

Location: GARVIN 3 4N 3W
SE SE NW SE
1170 FNL 1540 FEL of 1/4 SEC
Latitude: 34.844884444 Longitude: -97.4981036111
Derrick Elevation: 0 Ground Elevation: 0

First Sales Date:

Operator: GLB EXPLORATION INC 18634

7716 MELROSE LANE
OKLAHOMA CITY, OK 73127-6002

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	There are no Location Exception records to display.		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8 5/8	36	J-55	335		235	SURFACE
PRODUCTION	5.5	20	N-80	8650		425	6200

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 9377

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Feb 09, 2022	VIOLA	2	42	2	1000	642	FLOWING			

Completion and Test Data by Producing Formation			
Formation Name: VIOLA		Code: 202VIOL	Class: OIL
Spacing Orders		Perforated Intervals	
Order No	Unit Size	From	To
144855	160	7852	7908
Acid Volumes		Fracture Treatments	
4,500 GALLONS		170,000 POUNDS SAND, 5,500 BARRELS TREATED WATER	

Formation	Top
DEESE	6672
HUNTON	7083
VIOLA	7449

Were open hole logs run? Yes
Date last log run:

Were unusual drilling circumstances encountered? No
Explanation:

Other Remarks
There are no Other Remarks.

Bottom Holes
Sec: 3 TWP: 4N RGE: 3W County: GARVIN NW NE SW SE 1145 FSL 1730 FEL of 1/4 SEC Depth of Deviation: 0 Radius of Turn: 0 Direction: 0 Total Length: 0 Measured Total Depth: 9467 True Vertical Depth: 9450 End Pt. Location From Release, Unit or Property Line: 1145

FOR COMMISSION USE ONLY	
Status: Accepted	1148101

PLEASE TYPE OR USE BLACK INK ONLY

FORMATION RECORD

Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested.

LEASE NAME Lloyd WELL NO. #1

NAMES OF FORMATIONS	TOP
Viola	7449
Hunton	7083
Deese	6672

FOR COMMISSION USE ONLY

ITD on file ☐ YES ☐ NO

APPROVED _____ DISAPPROVED _____

2) Reject Codes

Were open hole logs run? ☒ yes ☐ no

Date Last log was run _____


Was CO₂ encountered? ☐ yes ☒ no at what depths? _____

Was H₂S encountered? ☐ yes ☒ no at what depths? _____

Were unusual drilling circumstances encountered? ☐ yes ☒ no

If yes, briefly explain below _____


Other remarks:



If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells



BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC 3	TWP 04N	RGE 03W	COUNTY	Garvin
NW 1/4 ne 1/4 SW 1/4 se 1/4		Feet From 1/4 Sec Lines FSL ∨ 1145 FEL ∨ 1730		
Measured Total Depth 9467		True Vertical Depth 9450		BHL From Lease, Unit, or Property Line: 1145

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

LATERAL #1

SEC	TWP	RGE	COUNTY
1/4	1/4	1/4	1/4
Feet From 1/4 Sec Lines		∨	∨
Depth of Deviation	Radius of Turn	Direction	Total Length
Measured Total Depth	True Vertical Depth	BHL From Lease, Unit, or Property Line:	

LATERAL #2

SEC	TWP	RGE	COUNTY
1/4	1/4	1/4	1/4
Feet From 1/4 Sec Lines		∨	∨
Depth of Deviation	Radius of Turn	Direction	Total Length
Measured Total Depth	True Vertical Depth	BHL From Lease, Unit, or Property Line:	

LATERAL #3

SEC	TWP	RGE	COUNTY
1/4	1/4	1/4	1/4
Feet From 1/4 Sec Lines		∨	∨
Depth of Deviation	Radius of Turn	Direction	Total Length
Measured Total Depth	True Vertical Depth	BHL From Lease, Unit, or Property Line:	