Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35087222700000 **Completion Report** Spud Date: November 17, 2019

OTC Prod. Unit No.: 087-226730-0-0000 Drilling Finished Date: January 05, 2020

1st Prod Date: March 27, 2020

Completion Date: March 15, 2020

First Sales Date: 3/27/20

Drill Type: HORIZONTAL HOLE

Well Name: CALVERT 0603-6-7 1WHX Purchaser/Measurer: ENABLE

MCCLAIN 31 7N 3W Location:

SE NE SE SE

762 FSL 223 FEL of 1/4 SEC

Latitude: 35.03180127 Longitude: -97.54823855 Derrick Elevation: 1215 Ground Elevation: 1195

WARWICK-BACCHUS LLC 24266 Operator:

> 6608 N WESTERN AVE BOX 417 OKLAHOMA CITY, OK 73116-7326

	Completion Type
Х	Single Zone
	Multiple Zone
	Commingled

Increased Density
Order No
712153
712154

		Cas	ing and Ceme	ent			
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	20			40			SURFACE
SURFACE	13.375	61	J-55	1508		950	SURFACE
PRODUCTION	5.5	23	P-110	21076		1715	6255

				Liner				
Type Size Weight Grade Length PSI SAX Top Depth Bottom Depth								
	-		There are	no Liner record	ds to displa	ay.		_

Total Depth: 21100

Pac	:ker				
Depth Brand & Type					
There are no Packe	er records to display.				

PI	ug
Depth	Plug Type
There are no Plug	records to display.

Initial Test Data

September 04, 2020 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Mar 27, 2020	WOODFORD	187	40	138	738	1124	PUMPING	1000	42/64	233

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders					
Order No	Unit Size				
685997	640				
685998	640				
713999	MULTIUNIT				

Perforated Intervals				
From	То			
10376	20994			

Acid Volumes
9,525 GAL HCL ACID

Fracture Treatments
569,424 BBLS FLUID 26,537,980 LBS PROPPANT

Formation	Тор
WOODFORD	9691

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 7 TWP: 6N RGE: 3W County: MCCLAIN

SE SW SE SW

127 FSL 1724 FWL of 1/4 SEC

Depth of Deviation: 9216 Radius of Turn: 805 Direction: 198 Total Length: 10618

Measured Total Depth: 21100 True Vertical Depth: 9863 End Pt. Location From Release, Unit or Property Line: 127

FOR COMMISSION USE ONLY

1145532

Status: Accepted

September 04, 2020 2 of 2