Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35103247440000 Completion Report Spud Date: October 19, 2018

OTC Prod. Unit No.: 103-224704 Drilling Finished Date: October 22, 2018

1st Prod Date: March 10, 2019

Completion Date: December 14, 2018

Drill Type: STRAIGHT HOLE

Well Name: TOMCAT 2 Purchaser/Measurer:

Location: NOBLE 31 24N 1W

NW NW NW SW 2475 FSL 215 FWL of 1/4 SEC

Derrick Elevation: 978 Ground Elevation: 965

Operator: DONRAY PETROLEUM LLC 21690

2525 NW EXPRESSWAY STE 640 OKLAHOMA CITY, OK 73112-7230

	Completion Type
Х	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

First Sales Date:

Casing and Cement												
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT					
SURFACE	8 5/8	23		378		200	SURFACE					
PRODUCTION	5.5	17		2460		185	1300					

Liner										
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth		
	There are no Liner records to display.									

Total Depth: 2460

Packer								
Depth	Brand & Type							
There are no Packer records to display.								

Plug								
Depth	Plug Type							
2460	CIBP							

	Initial Test Data												
Test Date	Formation	Oil Oil-Gravity Gas BBL/Day (API) MCF/Da			Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Flowing In Size			Flow Tubing Pressure			
Mar 12, 2019	HOOVER	3	40	10	3333	350	PUMPING	120					

May 23, 2019 1 of 2

Completion and Test Data by Producing Formation Formation Name: HOOVER Code: 406HOVR Class: OIL **Spacing Orders Perforated Intervals Order No Unit Size** From То NONE 2054 2066 **Acid Volumes Fracture Treatments** 750 GALLONS 12.5% HCL 870 BSW, 30,000 POUNDS 20/40 SAND

Formation	Тор
HOOVER	2000
OREAD	2350

Were open hole logs run? Yes
Date last log run: October 22, 2018

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

HAD TO WAIT ON ELECTRIC AND WEATHER IS REASON FOR COMPLETION DELAY.

FOR COMMISSION USE ONLY

1142572

Status: Accepted

May 23, 2019 2 of 2

filled through, and pertinent remarks are presented on the reverse. I declare that I have knowledge of the contents of this report and am authorized by my organization was prepared by me or under my supervision and direction, with the data and facts stated herein to be true, correct, and complete to the best of my knowledge and belief.

73112

ZIP

4/9/2019

DATE

ray@donraypetroleum.com

EMAIL ADDRESS

(405) 418-4348

PHONE NUMBER

ray corbitt jr

NAME (PRINT OR TYPE)

ok

STATE

okc

CITY

INITIAL SHUT-IN PRESSURE

FLOW TUBING PRESSURE

SIGNATURE

ADDRESS

525 nw expressway #640

A record of the for

CHOKE SIZE

120#

PLEASE TYPE OR USE BLACK INK ONLY
FORMATION RECORD
Give formation names and tops, if available, or descriptions and thickness of formations
drilled through. Show intends provide religible to the text.

Give formation names and tops, if available, or descriptions and thic drilled through. Show intervals cored or drillstem tested.							ble, or desc drillstem te	criptions and thic sted.	kness of formations	S	LEASE N	IAME		tomcat WELL NO					
		-	RMAT						ТОР					FOR	R COMMISSI	ON LISE OF	NI V		
										1	ITD on fil		7	ES NO	1 COMMISSI	014 032 01	NLI		
hoo	ver								2,000		APPROV			ISAPPROVED					
orea	ad								2350		AFFROV				2) Reject Co	des			
											Were ope	n hole logs	s run'	? <u>X</u> yes	no				
											Date Last	log was ru	ın		10/22/20	18			
											Was CO ₂	encounter	red?	yes	X no a	t what depti	hs?		
											Was H₂S	encountere	ed?		X no a				
											Were unu	sual drilling	g circ	cumstances encountere			yes)	(no	
											If yes, brid	efly explain	belo	v		-			
										_									
Other	rema	ırks:	ha	d to	wait	on e	lectric a	nd weather	is reason for	com	pletion delay								

					-														
Т		Г	640	Acres	<u> </u>	Т		BOTTOM H	OLE LOCATION	FOR [DIRECTIONAL HO	DLE							
+		\vdash	╀	╀	+	+	+	SEC	TWP	RGE		COUNTY							
\dashv		_	-	╀	\vdash	+	\vdash	Spot Locati	on 1/4	1/4	4/4			Feet From 1/4 Sec Lin	nes FS	SL	FW	/L	
\dashv		_	-	┡	\vdash	_	Ш	Measured 1	Total Depth	1/4	1/4 True Vertical De	pth	1/4	BHL From Lease, Unit		Line:	18888		
_			<u> </u>	<u>Ļ</u>		_													
\dashv								воттом н	IOLE LOCATION I	FOR H	IORIZONTAL HO	LE: (LATE	RAL	S)					
								LATERAL #				•		•					
						Π			TWP	RGE		COUNTY							
								Spot Location	on 1/4	1/4	4/4		4/4	Feet From 1/4 Sec Lin	es FS	 SL	FW		
more t	nan th	ree dr	ainhola	e ara n	ronono	d, attacl		Depth of	1/4	1/4	1/4 Radius of Turn		1/4	Direction		ital	I HEET HEET TO SEE THE		
						u, allaci nformati		Deviation Measured T	otal Depth		True Vertical De	oth		BHL From Lease, Unit		ngth Line:			
					s azimu														
oint mu	st be	located	within		le and i undarie	its end s of the		LATERAL #											
ase or		-						SEC	TWP	RGE		COUNTY							
irecti rainh	onai oles	surv	eys a direct	re red ional	uired wells	for al	I	Spot Location		1/4	1/4		1/4	Feet From 1/4 Sec Line	es FS	L	FW		
$\overline{}$	_		640	Acres	_			Depth of Deviation	.,.		Radius of Turn		_	Direction	To		Hillie		
+	_			_				Measured To	otal Depth		True Vertical Dep	oth	-	BHL From Lease, Unit,		ngth Line:			
\perp	4																		
\perp	\perp							LATERAL #				70-							
			,					SEC	TWP	RGE	1	COUNTY							
	T		,					Spot Location		1/4	1/4		1/4	Feet From 1/4 Sec Line	s FS	L	FWI		
	T							Depth of Deviation			Radius of Turn		1/4	Direction	Tot		Estable		
1	\forall							Measured To	otal Depth		True Vertical Dep	th	1	BHL From Lease, Unit,		ngth Line:			
+	\dashv	\dashv																	

tomcat

#2