Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35073261660001 **Completion Report** Spud Date: October 25, 2018

OTC Prod. Unit No.: 073-224881 Drilling Finished Date: December 11, 2018

1st Prod Date: January 15, 2019

Completion Date: January 15, 2019

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: THREE BIRDS 19-08-16 1MH Purchaser/Measurer: KINGFISHER MIDSTREAM

Location: KINGFISHER 16 19N 8W First Sales Date: 01/15/2019

N2 NW NW NW 210 FNL 330 FWL of 1/4 SEC

Latitude: 36.12999036 Longitude: -98.06720694 Derrick Elevation: 1227 Ground Elevation: 1209

Operator: CHISHOLM OIL & GAS OPERATING LLC 23991

> 6100 S YALE AVE STE 1700 TULSA, OK 74136-1921

Completion Type					
Х	Single Zone				
	Multiple Zone				
	Commingled				

Location Exception
Order No
694502

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement							
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	20			80			SURFACE
SURFACE	9 5/8	40	J-55	411		225	SURFACE
PRODUCTION	7	29	P-110	8168		275	5010

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4 1/2	13.5	P-110	4822	0	0	7992	12814

Total Depth: 12814

Packer				
Depth	Brand & Type			
8168 - 12814	SWELL PACKERS OPEN HOLE COMPLETION			

Plug					
Depth Plug Type					
There are no Plug records to display.					

Initial Test Data

October 28, 2019 1 of 3

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Feb 05, 2019	MISSISSIPPIAN (LESS CHESTER)	198	40	341	1722	1403	ESP		64/64	150

Completion and Test Data by Producing Formation

Formation Name: MISSISSIPPIAN (LESS

CHESTER)

Code: 359MSNLC

Class: OIL

Spacing Orders					
Order No	Unit Size				
686000	640				

Perforated Intervals				
From	То			
There are no Perf. Intervals records to display.				

Acid Volumes

47,333 GAL 15% HCL

Fracture Treatments

729,711 LBS 100 MESH SAND; 4,086,584 LBS 30/50 SAND

12,413,341 GAL SLICKWATER

Formation	Тор
CHECKERBOARD	6435
BIG LIME	6634
OSWEGO 3	6765
VERDIGRIS	6851
PINK LIME	6963
CHESTER	7170
MANNING	7297
MISSISSIPPIAN (LESS CHESTER)	7572
OSAGE	7618
OSAGE 4	7767
OSAGE 6 CHERT BENCH	7924
OSAGE 6B	7952

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

OCC – THIS IS AN OPEN HOLE COMPLETION FROM THE BOTTOM OF THE 7" AT 8168' TO TERMINUS AT 12814', THE 4 1/2 LINER IS NOT CEMENTED.

Lateral Holes

Sec: 16 TWP: 19N RGE: 8W County: KINGFISHER

SW SE SW SW

176 FSL 848 FWL of 1/4 SEC

Depth of Deviation: 7540 Radius of Turn: 403 Direction: 179 Total Length: 4640

Measured Total Depth: 12814 True Vertical Depth: 7993 End Pt. Location From Release, Unit or Property Line: 176

October 28, 2019 2 of 3

FOR COMMISSION USE ONLY

1142206

Status: Accepted

October 28, 2019 3 of 3