

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35015227260001

Completion Report

Spud Date: September 04, 2003

OTC Prod. Unit No.: 015-112168

Drilling Finished Date: September 25, 2003

Amended

1st Prod Date: November 26, 2003

Amend Reason: PERFORATE ADDITIONAL DEESE

Completion Date: November 25, 2003

Recomplete Date: July 29, 2022

Drill Type: STRAIGHT HOLE

Well Name: GROSS JR. 2-2

Purchaser/Measurer: SOUTHWEST

Location: CADD0 2 5N 9W
W2 W2 SE4 SW4
660 FSL 1495 FWL of 1/4 SEC
Latitude: 34.929278 Longitude: -98.123278
Derrick Elevation: 1433 Ground Elevation: 1415

First Sales Date: 8/5/2022

Operator: TERRITORY RESOURCES LLC 22388

1511 S SANGRE RD
STILLWATER, OK 74074-1869

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	477082		476677	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	20"			40			
SURFACE	13 3/8"	54.5	J55	850	2000	820	SURFACE
PRODUCTION	5 1/2"	17	N80	6549	3000	610	4365

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 6553

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Aug 11, 2022	DEESE			3			PUMPING	1320		

Completion and Test Data by Producing Formation									
Formation Name: DEESE				Code: 404DEESS			Class: GAS		
Spacing Orders				Perforated Intervals					
Order No		Unit Size		From			To		
226733		640		5130			5207		
				4916			5023		
Acid Volumes				Fracture Treatments					
ACIDIZE 4916-5023' WITH 70 BBLS 7.5% NEFE WITH CLAYSTAY				There are no Fracture Treatments records to display.					

Formation	Top
DEESE	4860
HOXBAR	3760

Were open hole logs run? Yes
Date last log run: September 23, 2003

Were unusual drilling circumstances encountered? No
Explanation:

Other Remarks
There are no Other Remarks.

FOR COMMISSION USE ONLY
<div>Status: Accepted</div> <div>1148730</div>