

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35049251970001

Completion Report

Spud Date: June 01, 2018

OTC Prod. Unit No.: 049-225543

Drilling Finished Date: July 12, 2018

1st Prod Date: July 25, 2019

Amended

Completion Date: May 09, 2019

Amend Reason: AMENDING TO RECLASSIFY AS A GAS WELL

Drill Type: HORIZONTAL HOLE

Well Name: BUD 1-12-1WXH

Purchaser/Measurer: WOODFORD EXPRESS

Location: GARVIN 13 3N 4W
NW NW NW NW
170 FNL 270 FWL of 1/4 SEC
Latitude: 34.738707 Longitude: -97.579332
Derrick Elevation: 1182 Ground Elevation: 1162

First Sales Date: 7/29/2019

Operator: CPRP SERVICES LLC 24506

123 NW 8TH ST
OKLAHOMA CITY, OK 73102-5804

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	703862		688079	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40.0	J-55	1512		443	SURFACE
PRODUCTION	5.5	20.0	P-110EC	23012		2115	6456

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 23012

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Dec 19, 2021	WOODFORD	9	46	1401	155660	205	GAS LIFT		64/64	916

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: GAS

Spacing Orders

Order No	Unit Size
677714	640
703861	MULTIUNIT

Perforated Intervals

From	To
12598	17750
17750	22867

Acid Volumes

810 BBLS HCL ACID

Fracture Treatments

588,042 BBLS FLUID 18,932,085 LBS PROPPANT

Formation	Top
WOODFORD	12340

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? Yes

Explanation: TWO SIDETRACKS DUE TO GEOLOGIC
INTEGRITY ISSUES, NO TOOLS LEFT DOWNHOLE.**Other Remarks**

There are no Other Remarks.

Lateral Holes

Sec: 1 TWP: 3N RGE: 4W County: GARVIN

NE NW NW NW

21 FNL 479 FWL of 1/4 SEC

Depth of Deviation: 12134 Radius of Turn: 330 Direction: 1 Total Length: 10269

Measured Total Depth: 23012 True Vertical Depth: 11692 End Pt. Location From Release, Unit or Property Line: 21

FOR COMMISSION USE ONLY

1147830

Status: Accepted