

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35087220890001

Completion Report

Spud Date: November 24, 2017

OTC Prod. Unit No.: 087-223183

Drilling Finished Date: December 25, 2017

1st Prod Date: March 13, 2018

Completion Date: February 08, 2018

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: COOP 1-33-4WXH

Purchaser/Measurer: ENABLE

Location: MCCLAIN 34 6N 4W
NW NW NW NW
174 FNL 179 FWL of 1/4 SEC
Latitude: 34.956472 Longitude: -97.616887
Derrick Elevation: 0 Ground Elevation: 1169

First Sales Date: 3/21/2018

Operator: CASILLAS OPERATING LLC 23838

401 S BOSTON AVE STE 2400
TULSA, OK 74103-4060

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	681424		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9 5/8	40.00	J-55	1485		375	SURFACE
PRODUCTION	5 1/2	20.00	P-110EC	21334		2110	16533

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 21334

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
May 02, 2018	WOODFORD	591	45	339	574	1782	FLOWING			200

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders

Order No	Unit Size
669738	640
664054	640
681423	MULTIUNIT

Perforated Intervals

From	To
11271	21237

Acid Volumes

504 BBLS ACID

Fracture Treatments

605,769 BBLS FLUID & 24,999,762 LBS PROPPANT
--

Formation	Top
WOODFORD	10990

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 4 TWP: 5N RGE: 4W County: MCCLAIN

SW SE SE SE

203 FSL 398 FEL of 1/4 SEC

Depth of Deviation: 10794 Radius of Turn: 590 Direction: 180 Total Length: 9950

Measured Total Depth: 21334 True Vertical Depth: 11055 End Pt. Location From Release, Unit or Property Line: 203

FOR COMMISSION USE ONLY

Status: Accepted

1138988