# Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

OTC Prod. Unit No.: Drilling Finished Date: October 11, 2019

1st Prod Date:

First Sales Date:

Completion Date: October 28, 2019

Drill Type: STRAIGHT HOLE

**SERVICE WELL** 

Well Name: KINGFISHER SWD 1 Purchaser/Measurer:

Location: KINGFISHER 20 16N 7W

SW NW NE NE 575 FNL 1170 FEL of 1/4 SEC

Derrick Elevation: 0 Ground Elevation: 1060

Operator: OVERFLOW ENERGY LLC 22383

PO BOX 354 111 S MAIN

**Completion Type** 

Single Zone

Multiple Zone

Commingled

BOOKER, TX 79005-0354

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement									
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT		
SURFACE	9 5/8	36	J-55	503		280	SURFACE		
PRODUCTION	7	26	P-110 / J-55	5948		995	3060		

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 6007

Packer					
Depth	Brand & Type				
3351	AS1X				

Plug						
Depth Plug Type						
There are no Plug records to display.						

**Initial Test Data** 

January 17, 2020 1 of 3

Test Date	Forma		/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubin
						a records to disp	-				
			Comp	letion and	Test Data	by Producing F	ormation				
	Formation N	Name: WABAUNSE	E		Code: 40	06WBNS	C	lass: COMM	DISP		
	Spacing	g Orders				Perforated In	ntervals				
Orde	r No	Unit Siz	е		Fror	n	7	Го	$\neg$		
There are	e no Spacing C	Order records to dis	play.		396	0	41	172			
	Acid V	olumes		$\neg \sqcap$		Fracture Tre	atments				
	5,000 GALLC	ONS 20% HCL				NONE					
	Formation N	Name: SHAWNEE			Code: 40	06SHWN	C	lass: COMM	DISP		
Spacing Orders					Perforated Intervals						
Orde	r No	Unit Siz	е		From To						
There are no Spacing Order records to display.					4328 4500						
	Acid V	olumes		$\neg \sqcap$	Fracture Treatments						
There a	re no Acid Volu	ume records to disp	olay.		here are no	Fracture Treatn	nents record	s to display.			
	Formation N	Name: DOUGLAS			Code: 40	06DGLS	C	class: COMM	DISP		
	Spacing	g Orders				Perforated In	ntervals				
Order No Unit Size			7	Fror	n	7	Го				
There are no Spacing Order records to display.  Acid Volumes				456	0	59	972				
			$\neg \vdash$	Fracture Treatments							
There are no Acid Volume records to display.					There are no Fracture Treatments records to display.						
ormation			Тор	ı		Vere open hole I	ogs run? No	ı			
WABAUNSEE				3850 Date last log run: October 23, 2019							
SHAWNEE					4200 Were unusual drilling circumstances encountered? No						
DOUGLAS						Explanation:					

Other Remarks
ORDER NUMBER 689966. DV TOOL @ 3.400'. 4 1/2" TUBING @ 3.351'

January 17, 2020 2 of 3

## FOR COMMISSION USE ONLY

1144540

Status: Accepted

January 17, 2020 3 of 3

TX

STATE

79005

ZIP

permitting@oeswd.com

**EMAIL ADDRESS** 

Booker

CITY

PO Box 354

ADDRESS


## PLEASE TYPE OR USE BLACK INK ONLY FORMATION RECORD

Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested.

Wabaunsee Shawnee Douglas  3,850' 4,200' 4,550'	NAMES OF FORMATIONS	TOP
	Shawnee dead of a sub-off off additional and a sub-off a sub-off and a sub-off and a sub-off a s	4,200'

	FOR COMMISSION USE ONLY	
TD on file YES	NO	
APPROVED DISAPPRO	OVED 2) Reject Codes	
	yes _X no	
Vere open hole logs run?		
	10-23-19 (RCBL)	
Were open hole logs run?  Date Last log was run  Was CO <sub>2</sub> encountered?		
Date Last log was run	10-23-19 (RCBL)	

Other remarks:	UIC: 1706120040	Order #:689966	DV Tool @ 3,400' 4 1/2" tubing @ 3,351'
	. v	3	



If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth.
Please note, the horizontal drainhole and its end
point must be located within the boundaries of the
lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.

0	640 Acres											

#### BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC TWP	RGE	COUNTY			
Spot Location	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Measured Total Depth		True Vertical Depth	BHL From Lease, Unit, or Pr		

### BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

SEC T TWP RGE COUNTY Feet From 1/4 Sec Lines Spot Location FWL FSL 1/4 1/4 Total Radius of Turn Direction Depth of BHL From Lease, Unit, or Property Line: Deviation Measured Total Depth True Vertical Depth

SEC	TWP	RGE	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	COUNTY					
Spot Loc	ation 1/4	1/4	1/4	1	1/4	Feet From 1/4 Sec Lines	FSL		FWL
Depth of Deviation			Radius of Turn		_	Direction	Total Length		
	fleasured Total Depth True Vertical Depth				BHL From Lease, Unit, or Property Line:				

SEC	TWP	RGE		COUNTY			
Spot Loca	ation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation			Radius of Turn		Direction	Total Length	
Measured Total Depth True Vertical Dep			pth	BHL From Lease, Unit, or Property Line:			