

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35051247680002

Completion Report

Spud Date: June 04, 2021

OTC Prod. Unit No.: 051-227394-0-0000

Drilling Finished Date: June 22, 2021

1st Prod Date: August 23, 2021

Completion Date: August 08, 2021

Drill Type: HORIZONTAL HOLE

Well Name: REBA MCENTIRE 1006 29-32-1MXH

Purchaser/Measurer: ENLINK

Location: GRADY 29 10N 6W
S2 N2 NW NW
380 FNL 660 FWL of 1/4 SEC
Latitude: 35.3187235 Longitude: -97.86324725
Derrick Elevation: 0 Ground Elevation: 1272

First Sales Date: 8/23/21

Operator: CAMINO NATURAL RESOURCES LLC 24097

1401 17TH ST STE 1000
DENVER, CO 80202-1247

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	720611		719177	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9 5/8	36	J55	1515	4230	510	SURFACE
PRODUCTION	5.5	20	P110EC	20821	12090	2748	17821

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 20830

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Aug 27, 2021	MISSISSIPPIAN	283	46	3707	13093	1507	FLOWING	1270	34	1337

Completion and Test Data by Producing Formation

Formation Name: MISSISSIPPIAN

Code: 359 MSSP

Class: OIL

Spacing Orders

Order No	Unit Size
275514	640
668352	640
720610	MULTIUNIT

Perforated Intervals

From	To
10515	15637
15637	20754

Acid Volumes

250 GAL 15% HCL

Fracture Treatments

591,881 BBLS FLUID; 27,293,020# PROP

Formation	Top
MISSISSIPPIAN	10343

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 32 TWP: 10N RGE: 6W County: GRADY

SE SW SW SW

97 FSL 419 FWL of 1/4 SEC

Depth of Deviation: 9923 Radius of Turn: 471 Direction: 91 Total Length: 10002

Measured Total Depth: 20830 True Vertical Depth: 10664 End Pt. Location From Release, Unit or Property Line: 97

FOR COMMISSION USE ONLY

1146928

Status: Accepted