

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35051248190000

Completion Report

Spud Date: August 08, 2021

OTC Prod. Unit No.: 051-228009-0-0000

Drilling Finished Date: October 14, 2021

1st Prod Date: May 26, 2022

Completion Date: May 26, 2022

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: TODD 1H-27-34

Purchaser/Measurer: BLUE MOUNTAIN
MIDSTREAM

First Sales Date: 5/26/2022

Location: GRADY 26 10N 5W
NW SE SW NW
2284 FNL 904 FWL of 1/4 SEC
Latitude: 35.31365857 Longitude: -97.70288987
Derrick Elevation: 1234 Ground Elevation: 1209

Operator: CITIZEN ENERGY III LLC 24120

320 S BOSTON AVE STE 900
TULSA, OK 74103-3729

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	727752		726320	
	Commingled			726321	

Casing and Cement								
Type		Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE		9.625	40	J-55	1011		270	SURFACE
PRODUCTION		7	29	P-110	8746		312	4515

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4.5	13.5	P-110	8694	0	567	8535	17229

Total Depth: 17229

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jun 10, 2022	WOODFORD	528	41.8	1436	2720	1484	FLOWING	1775	30	1089

Completion and Test Data by Producing Formation	
Formation Name: WOODFORD	Code: 319WDFD
Class: OIL	

Spacing Orders	
Order No	Unit Size
419868	640
415281	640
727751	MULTIUNIT

Perforated Intervals	
From	To
9518	17176

Acid Volumes
20,012 GALLONS OF 15% HCl

Fracture Treatments
19,623,208 POUNDS OF PROPPANT 441,083 BARRELS OF FRAC FLUID

Formation	Top
WOODFORD	8975

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks
There are no Other Remarks.

Lateral Holes
Sec: 34 TWP: 10N RGE: 5W County: GRADY SW SE SE SE 119 FSL 642 FEL of 1/4 SEC Depth of Deviation: 8818 Radius of Turn: 404 Direction: 176 Total Length: 8172 Measured Total Depth: 17229 True Vertical Depth: 9167 End Pt. Location From Release, Unit or Property Line: 119

FOR COMMISSION USE ONLY	
Status: Accepted	1148479