

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35087223220000

Completion Report

Spud Date: October 04, 2021

OTC Prod. Unit No.: 087-227608

Drilling Finished Date: November 08, 2021

1st Prod Date: January 29, 2022

Completion Date: January 20, 2022

Drill Type: HORIZONTAL HOLE

Well Name: CHOATE 0504 03-10-3WXH

Purchaser/Measurer: ENABLE/ONEOK

Location: MCCLAIN 3 5N 4W
SW NW NE SE
2290 FSL 1039 FEL of 1/4 SEC
Latitude: 34.934181 Longitude: -97.603581
Derrick Elevation: 1152 Ground Elevation: 1128

First Sales Date: 1/29/2022

Operator: CPRP SERVICES LLC 24506

123 NW 8TH ST
OKLAHOMA CITY, OK 73102-5804

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	724148		721640	
	Commingle			721393	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40	J-55	3478		630	SURFACE
PRODUCTION	5.5	20	P-110	18350		2000	SURFACE

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 18355

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Mar 11, 2022	WOODFORD	1084	46	1125	1038	1267	GAS LIFT		128/128	1636

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders

Order No	Unit Size
671208	640
656736	640
724147	MULTIUNIT

Perforated Intervals

From	To
11036	13240
13240	18254

Acid Volumes

There are no Acid Volume records to display.
--

Fracture Treatments

22,503,138 GALLONS WATER 17,864,572 LBS PROPPANT

Formation	Top
WOODFORD	10745

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 10 TWP: 5N RGE: 4W County: MCCLAIN

SW SE SE SE

201 FSL 366 FEL of 1/4 SEC

Depth of Deviation: 10415 Radius of Turn: 621 Direction: 180 Total Length: 7319

Measured Total Depth: 18355 True Vertical Depth: 10857 End Pt. Location From Release, Unit or Property Line: 201

FOR COMMISSION USE ONLY

1148083

Status: Accepted